

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006767/APA3Q2**Date:** 22/09/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800135905
Claimant Vehicle No :	SLK9187K	Insured Vehicle No :	SMF6396H
Date of Loss:	09/07/2022	Nature of Claim:	TP
		Claim No:	5708848149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK9187K	Engine No:	1ZRY294924
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104551439
Reg. Date:	06/02/2017 (Man. Year: 2016)	Odometer:	52552 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,138.55	3,498.57	6,639.98	65.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	600.00	1,190.00	66.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,928.55	4,098.57	7,829.98	65.64
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	11,928.55	3,200.00	8,728.55	73.17
+ GST 7.00/7.00% (S\$)	835.00	224.00	611.00	73.17
Nett Amount (S\$)	12,763.55	3,424.00	9,339.55	73.17
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		3,664.00		

INSPECTION

Date of Assignment:	14/07/2022	Mirage Motorwerkz Pte Ltd (HQ)
Date Inspected:	14/07/2022 Inspected At:	10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST CENTRE
Estimated Period of Repair:	3.0 days	Singapore 417868

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	581.10 FL	*581.10 FL
2	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	110.20 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Deformed	148.60 FL	*148.60 FL
4	2		*FRONT BUMPER FOG LAMP	Not Necessary	578.80 FL	*- FL
5	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	156.80 FL	*- FL
6	1		*FRONT BUMPER REINFOROCEMENT	Not Necessary	395.70 FL	*- FL
7	1		*FRONT GRILLE	Cut	425.40 FL	*425.40 FL
8	1		*FRONT GRILLE LOGO	Necessary	75.30 FL	*75.30 FL
9	1		*FRONT GRILLE TOP COVER	Not Necessary	80.70 FL	*- FL
10	1		*HEADLAMP	O/S Cracked	5,633.00 FL	*2,816.50 FL
11	1		*HEADLAMP TOP CHROME	O/S Necessary	306.40 FL	*153.20 FL
12	1		*FRONT BRACE PANEL	Not Necessary	182.10 FL	*- FL
13	1		*FRONT SUPPORT PANEL	Not Necessary	891.50 FL	*- FL
14	1		*AIR CON CONDENSER	Not Necessary	1,507.40 FL	*- FL
15	1		*RADIATOR	Not Necessary	1,780.40 FL	*- FL
16	1		*FRONT BUMPER SPONGE	Cracked	118.00 FL	*118.00 FL
17	1		*FRONT NUMBER PLATE	Dented	30.00 FS	*30.00 FS
18	1		*FRONT NUMBER PLATE HOLDER	Dented	30.00 FS	*30.00 FS
19	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*FRONT BUMPER LOWER GRILLE MOULDING	Deformed	200.00 FS	*150.00 FS
21	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
22	1		*SET FRONT GRILLE TOP COVER CLIPS	Not Necessary	20.00 FS	*- FS
23	1		*BOT COOLANT	Not Necessary	60.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	13,381.40 4,578.10
					- List Item Discount on L Items 25.00/25.00% (\$\$)	3,242.85 1,079.53
					Total Parts (\$\$)	10,138.55 3,498.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	300.00
2	SPRAY PAINTING	New	600.00	250.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	100.00	20.00
5	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	New	120.00	0.00
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	New	120.00	0.00
Gross Labour Cost (\$\$)			1,790.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >