

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCA 3200D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEADLAMP R	NOT NECESSARY	2,205.54	-
1	R FRONT FENDER	BENT	731.10	731.10
1	R FRONT FENDER INNER SHIELD	NOT NECESSARY	129.07	-
1	R FRONT BUMPER	TO REPAIR SEE LABOUR	1,390.02	-
1	R FRONT BUMPER RETAINER	NOT NECESSARY	93.42	-
	LESS 10% DISCOUNT		-454.92	-73.11
			4,094.23	657.99
	<u>LABOUR</u>			
	TO SPRAY PAINTING ON AFFECTED AREA.		400.00	400.00
	TO REPLACE AND REFIX FENDER AND BUMPER AND ALIGNMENT AND FITTING. INCLUSIVE OF THE REPAIR OF R FRONT BUMPER.		350.00	300.00
	TO REPLACE AND REFIX HEADLAMP AND FITTING AND ALIGNMENT.	NOT NECESSARY	150.00	-
	TO REPLACE BUMPER MECHANISM.	NOT NECESSARY	150.00	-
	TO CHECK WIRING FOR HEADLAMP.	NOT NECESSARY	120.00	-
	TO COMPUTER SETTING FOR WHOLE VEHICLE.	NOT NECESSARY	160.00	
			1,330.00	700.00
	GRAND TOTAL		5,424.23	1,357.99

RECOMMENDED COST OF LUMP SUM REPAIRS		1,050.00
(REPAIR COST NOT CONCLUDE)		

Report Ref No. CS/SMR22006771/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator