

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006777/UPA3Q2**Date:** 10/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900254866-02
Claimant Vehicle No :	FBL65B	Insured Vehicle No :	GBH1442K
Date of Loss:	08/07/2022	Nature of Claim:	TP
		Claim No:	2732131806SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL65B	Engine No:	E3F5E041620
Make & Model:	YAMAHA YBR125, 124cc (M)	Chassis No:	LBPRI101000056382
Reg. Date:	30/04/2016 (Man. Year: 2016)	Odometer:	76055 km
Colour:	Red		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	3.00-18
Front Left Side:	Timsun 6 mm	Rear Left Side:	Timsun 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	231.00	167.50	63.50	27.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	166.00	80.00	86.00	51.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	397.00	247.50	149.50	37.66
Approved Total (Overridden) (\$\$)		200.00		
(\$\$)	397.00	200.00	197.00	49.62
+ GST 7.00/7.00% (\$\$)	27.79	14.00	13.79	49.62
Nett Amount (\$\$)	424.79	214.00	210.79	49.62
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	18/07/2022		
Date Inspected:	18/07/2022	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COWLING FRONT (RED)	Cut	112.00 F	*112.00 FL
2	1		*LAMP SIGNAL FRONT LH (Scratched)	Not Consistent With The Impact	21.00 F	*- FL
3	1		*MUDGUARD FRONT (RED)	Cut	49.00 F	*49.00 FL
4	1		*STICKER (MCDONALDS) ACCIDENTAL	Necessary	14.00 F	*14.00 FL
5	1		*STICKER (MCDONALDS) WINDSHIELD V2	Not fitted	16.00 F	*- FL
6	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	19.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	231.00	185.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	17.50
Total Parts (S\$)	231.00	167.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES	New	40.00	0.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	126.00	80.00
Gross Labour Cost (\$)			166.00	80.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >