

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22006779/KQY3Q2**Date:** 19/01/2023**REFERENCE**

Insured/Claimant: WANG DAJIE CHRISTOPHER Policy No: SP2000525565
Date of Loss: 14/07/2022 Nature of Claim: OD Claim No: 202222005610

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV2385G**
Make & Model: MERCEDES-BENZ GLB200, 1.3 (A) Engine No: 28291480302829
Reg. Date: 22/09/2020 (Man. Year: 2020) Chassis No: W1N2476872W039346
Colour: Metallic Red Odometer: 39677 km
Engine Capacity: 1332 cc
Market Value/New Car Price: S\$188,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/50 R19 Rear Tyre Size: 235/50 R19
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,573.80	4,892.40	13,681.40	73.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	1,100.00	3,150.00	74.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,823.80	5,992.40	16,831.40	73.74
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	22,223.80	5,392.40	16,831.40	75.74
+ GST 7.00/7.00% (S\$)	1,555.67	377.47	1,178.20	75.74
Nett Amount (S\$)	23,779.47	5,769.87	18,009.60	75.74

INSPECTION

Date of Assignment: 16/07/2022
Date Inspected: 19/07/2022 Inspected At: 160 SIN MING DRIVE #06-03 SIN MING CITY
Estimated Period of Repair: 4.0 days Repairer: MBM Wheelpower Pte Ltd (Sin Ming)

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2023)	
Parts: M1-SUV	MERCEDES-BENZ GLB200 1.3 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SMV2385G)		
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,900.00 FL	*2,150.00 FL
2	1		*BONNET WEATHERSTRIP	Serviceable	350.00 FL	*- FL
3	1		*BONNET HINGE LH	Repair	118.00 FL	*- FL
4	1		*BONNET HINGE RH	Repair	118.00 FL	*- FL
5	1		*BONNET STAY LH	Serviceable	125.00 FL	*- FL
6	1		*BONNET STAY LH	Serviceable	125.00 FL	*- FL
7	1		*BONNET LOCK	Repair	142.00 FL	*- FL
8	1		*BONNET LOCK CABLE	Serviceable	77.00 FL	*- FL
9	1		*BONNET LOCK STRIKER	Repair	60.00 FL	*- FL
10	1		*BONNET LOGO	Necessary	56.00 FL	*56.00 FL
11	1		*HEADLAMP LH	Serviceable	3,700.00 FL	*- FL
12	1		*HEADLAMP RH	Mtg Cracked	3,600.00 FL	*1,960.00 FL
13	1		*FRONT BUMPER	Repair	2,450.00 FL	*- FL
14	1		*FRONT BUMPER SPONGE	Serviceable	160.00 FL	*- FL
15	1		*FRONT BUMPER REINFORCEMENT	Repair	650.00 FL	*- FL
16	1		*FRONT BUMPER RETAINER LH	Serviceable	75.00 FL	*- FL
17	1		*FRONT BUMPER RETAINER RH	Serviceable	75.00 FL	*- FL
18	1		*FRONT BUMPER TOWING COVER	Serviceable	130.00 FL	*- FL
19	10		*FRONT BUMPER CLIP	Not Necessary	80.00 FL	*- FL
20	1		*FRONT BUMPER LOWER CENTER GRILLE	Serviceable	480.00 FL	*- FL
21	1		*FRONT RADIATOR GRILLE	Serviceable	1,120.00 FL	*- FL
22	1		*FRONT PROTECTIVE GRILLE	Serviceable	500.00 FL	*- FL
23	1		*FRONT RADIATOR GRILLE MERCEDES LOGO }	Serviceable	185.00 FL	*- FL
24	1		*FRONT RADIATOR GRILLE EMBLEM }	Serviceable	0.00 FL	*- FL
25	1		*FRONT PROTECTIVE GRILLE TRIM	Serviceable	90.00 FL	*- FL
26	1		*FRONT PROTECTIVE GRILLE TRIM	Serviceable	110.00 FL	*- FL
27	1		*FRONT RADAR SENSOR	Serviceable	1,400.00 FL	*- FL
28	1		*FRONT CAR PLATE GARNISH	Dented	140.00 FL	*140.00 FL
29	1		*SUPPORT PANEL	Cracked	730.00 FL	*730.00 FL
30	1		*FRONT AIRDUCT SEGMENT	Serviceable	340.00 FL	*- FL
31	1		*CONDENSER	Serviceable	26.00 FL	*- FL
32	1		*RADIATOR	Serviceable	70.00 FL	*- FL
33	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS
34	1		*SUPPORT PANEL TOP GARNISH	Cracked	250.00 FL	*250.00 FL
35	1		*FRONT SHUTTER GRILLE	Mtg Cracked	150.00 FL	*150.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,632.00	5,436.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,058.20	543.60
Total Parts (\$\$)	18,573.80	4,892.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS ,INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,600.00	600.00
2	TO REMOVE,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	200.00	0.00
3	TO CALIBRATE RADAR SENSOR	New	350.00	0.00
4	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	200.00	20.00
5	TO REMOVE & REFIT ALL SENSOR	New	250.00	0.00
6	TO RESET ENGINE WARNING LIGHT (ABS ,SRS ,ECU MEMORY & ETC)	New	250.00	0.00
7	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,400.00	480.00
Gross Labour Cost (S\$)			4,250.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >