

Vehicle Damage Assessment Report for [SMN3811D]

Estimate Created: 19/07/2022 01:54 by LKK_assignments
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 15/06/2023 10:49 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	India International Insurance	Claim Number	MFL2022D0003656
Claim Type	OD		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Nissan	Model	Qashqai
Engine Type			
License Plate Number	SMN3811D	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$25,245.70 AND 10 WORKING DAYS. Insurlogic 4 (15/06/2023 10:32)

- Supp item review done base on survey information provided
Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Note: Align with LKK surveyor assessment, however labour and painting been adjusted, please refer as follow. Insurlogic 1 (29/08/2022 02:36)

Supp items review by : Insurlogic
Parts : \$2319.30

- Pre review by insurlogic:

Parts : \$18174.60
Labour : \$2630.00
Total: \$20804.60
Repair days: 10

Insurlogic 4 (22/07/2022 04:00)

check item(before discount) : \$1673.00

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
FRT BUMPER		1	737.00	-10.00 %	663.30
FRT BUMPER RETAINER LH		1	26.00	-10.00 %	23.40
FRT BUMPER CLIP		10	5.00	-10.00 %	45.00
FRT BUMPER COVER LH		1	120.00	-10.00 %	108.00
FRT LH FENDER		1	739.00	-10.00 %	665.10
FRT LH FENDER INNER SHIELD		1	139.00	-10.00 %	125.10
FRT LH FENDER INNER SHIELD CLIP		1	40.00	-10.00 %	36.00
FRT LH FENDER ARCH GARNISH		1	584.00	-10.00 %	525.60
LH HEADLAMP		1	3496.00	-10.00 %	3,146.40
FRT LH RIM		1	1333.00	-10.00 %	1,199.70
FRT LH RIM CENTER NISSAN CAB		1	36.00	-10.00 %	32.40
FRT LH DOOR		1	1259.00	-10.00 %	1,133.10
FRT LH DOOR OUTER LOWER GARNISH		1	370.00	-10.00 %	333.00
FRT LH DOOR FRAME WEATHER BLACK STICKER		1	35.00	-10.00 %	31.50
FRT LH DOOR FRAME TOP BLACK STICKER		1	45.00	-10.00 %	40.50
FRT LH KUNCKLE ARM		1	602.00	-10.00 %	541.80
FRT LH LOWER ARM		1	269.00	-10.00 %	242.10
FRT LH WHEEL HUB WITH BEARING		1	310.00	-10.00 %	279.00
FRT LH SHOCK ABSORBER TOP MOUNTING		1	112.00	-10.00 %	100.80
FRT LH STEERING TIE ROD END		1	129.00	-10.00 %	116.10
LH FRT SEAT AIRBAG		1	1399.00	-10.00 %	1,259.10
LH FRT SEAT BACKREST CUSHION COVER		1	2124.00	-10.00 %	1,911.60
LH FRT SEAT BACKREST CUSHION		1	1066.00	-10.00 %	959.40
LH ROOF TOP AIRBAG		1	1867.00	-10.00 %	1,680.30
ROOF TOP LINING COVER		1	1426.00	-10.00 %	1,283.40
AIRBAG CONTROL UNIT		1	1560.00	-10.00 %	1,404.00
FRT LH SEAT AIRBAG SENSOR		1	450.00	-10.00 %	405.00

FRT LH ABSORBER	1	607.00	-10.00 %	546.30
FRT STEERING RACK	1	1590.00	-10.00 %	1,431.00
FRT ENGINE UNDERCOV	1	334.00	-10.00 %	300.60
REAR LH SEAT HANDLE COVER	1	6.00	-10.00 %	5.40
FRONT RH ENGINE MOUNTING	1	427.00	-10.00 %	384.30
FRONT LH SEAT BELT	1	788.50	0.00 %	788.50
FRONT LH TYRE PRESSURE SENSOR	1	165.00	-10.00 %	148.50
FRONT FENDR COWLING LH	1	98.00	-10.00 %	88.20
FRONT LH SEAT BELT PILLAR TRIM	1	60.00	-10.00 %	54.00
LH SIDE AIRBAG SENSOR	1	367.20	0.00 %	367.20

Parts Subtotal 22,404.70

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRT LH TYRE		1.0	200.00	0.00 %	200.00
OD/TP Case (Insurer)		1.0	11.00	0.00 %	11.00

Materials Subtotal 211.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING	RnR	750.00	0.00 %	750.00
TO DISMANTLE FRT LH SUSPEION UNIT TO ASSIST REPAIR AND REPLACE DAMAGE PARTS	RnR	200.00	0.00 %	200.00
WHEEL ALIGNMENT	RnR	80.00	0.00 %	80.00
TO REMOVE LH FRT SEAT TO REPLACE CUSHION AND AIRBAG	RnR	150.00	0.00 %	150.00
TO REMOVE AND REPLACE ROOF TOP LINING AND CURTAIN AIRBAG	RnR	100.00	0.00 %	100.00
TO REPROGRAM ECU AND AIRBAG SYSTEM	RnR	250.00	0.00 %	250.00
TO TRANSFER DOOR PART TO NEW DOOR	RnR	80.00	0.00 %	80.00
CHECK LIGHTING AND WIRING	RnR	20.00	0.00 %	20.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
-------------	----------	------	---------------	-------

FRT LH DOOR HINGE LOWER	Medium	0.00	0.00 %	0.00
FRT LH DOOR HINGE TOP	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING	Full spray	1000.00	0.00 %	1,000.00
Labor Rate	S\$ 50 / Hour		General Labor Subtotal	1,630.00
			Paint Labor Subtotal	1,000.00
			Labor Subtotal	2,630.00

Summary

Repair Cost	25,245.70
Discount(0 %)	(0.00)
	25,245.70
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	25,245.70