

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22006786/Evy3m4 8 SHENTON WAY #24-01 AXA TOWER Date: 22/07/2022 SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SLX 5012P SMQ 770S** Veh. Inspected Policy No. GA534068 Coverage (\$) 0.00 Claim No. S2M046S4 Excess (\$) 0.00 ANG YVONNE 18/07/2022 Assign From Assign Date **Vehicle Particulars & Condition** 2. VOLVO S60 Make & Model 1969 C.C HIDDEN 2019 Engine No. Year of Reg. 7JRZS10ACLG036757 RED Chassis No. Colour Odometer 30782 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 235/45 R18 CONTINENTAL 5 mm CONTINENTAL L/H Front Tyre 235/45 R18 5 mm 235/45 R18 CONTINENTAL R/H Rear Tyre 5 mm CONTINENTAL L/H Rear Tyre 235/45 R18 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 15/07/2022 Inspect Date / Time 20/07/2022 (08:50 PM) Accident Date **JSSPRAYWERKS** Survey held at 5035 ANG MO KIO INDUSTRIAL PARK 2, #01-355, ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22006786/Evy3m4

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days