

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 8347R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	TO REPAIR SEE LABOUR	2,182.29	-
1	TAILGATE EMBLEM LOGO	NOT NECESSARY	239.85	-
2	TAILLAMP @\$647.24	N/S BROKEN	1,294.48	647.24
1	REAR BUMPER	DENTED / BROKEN	1,638.01	1,250.00
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.72	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	754.65	-
1	REAR BUMPER CENTER GUARD	BROKEN	126.66	126.66
2	REAR BUMPER SIDE HOLDER @\$377.35	N/S BROKEN	754.70	165.00
2	REAR BUMPER RETAINER @\$377.35	SERVICEABLE	754.70	-
1	SMART OPENING SENSOR	DAMAGED	104.00	104.00
1	SMART OPENING SENSOR HOLDER	BROKEN	143.26	143.26
1	SMART OPENING CONTROL UNIT	NOT NECESSARY	1,100.88	-
4	REAR PARKING SENSOR @\$417.93	DAMAGED (2PCS ONLY)	1,671.72	470.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,096.53	-
	LESS 5% DISCOUNT		-597.77	-145.31
			11,357.68	2,760.85
	SPECIAL NETT ITEMS			
1	TAILGATE GLASS SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	58.00	40.00
			158.00	40.00
	<u>LABOUR</u>			
	LABOUR TO REPAIR & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL.		700.00	400.00
	TO RESPRAY PAINTING ON ACCIDENT PORTION.		900.00	450.00
	TO REMOVE, REPLACE PARKING SENSOR.		80.00	60.00
	TO CHECK WIRING.		20.00	20.00

Report Ref No. CS3/LPC22003300/Vqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO DIAGNOSE & RESET SYSTEM AFTER REPAIR.	NOT NECESSARY	420.00	-
			2,120.00	930.00
	GRAND TOTAL		13,635.68	3,730.85

RECOMMENDED COST OF LUMP SUM REPAIRS		3,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/LPC22003300/Vqy3e2-1

B

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator