Constant Appraiser Services Qualified Automobile Accident Damage Appraisers/Loss Adjusters Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234 Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: Jolie Dion c/o Blk 2 Kaki Bukit Avenue 2 #02-32 Kaki Bukit Auto Hub Singapore 417921

Date

: 22/04/2022

CL

Invoice No

: IV22-04013/CAS

Particulars .	Amount	
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SKX 8347R (Inclusive Of Photographs And Transport Charges) Our reference: CAS/22-04/013	\$711.00	
Total	\$711.00	

E. & O.E

Constant Appraiser Services



Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters Blk 2 Rivervale Link, #09-02 Singapore 545040 Tel/Fax: 6886 1106 Mobile: 9007 5234 Email: constant_as@yahoo.com.sg RCB No. 53138015K

Automobile Inspection Report

To: Jolie Dion

c/o Blk 2 Kaki Bukit Avenue 2 #02-32 Kaki Bukit Auto Hub

Singapore 417921

Date

: 22/04/2022

Reference No : CAS/22-04/013

General Information

Registration No.

SKX 8347R

Accident Date

04/04/2022

Particulars of Damaged Vehicle

Colour

Grey

Make & Model

: BMW 216D

Engine Capacity

1496 cc

Pre-Accident Condition

Good

Mileage (KM)

198255

Engine No.

32139364B37C15A

Chassis No.

: WBA2B32090V259765

Steering

: In Order

Registration Date : 29/12/2015

Brake

: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	205/55R16	BRIDGESTONE	90%
L/H Front Tyre	205/55R16	BRIDGESTONE	90%
R/H Rear Tyre	205/55R16	KUMHO	90%
L/H Rear Tyre	205/55R16	KUMHO	90%

Inspection

Repairer

: Chng Brother Motor Services

Blk 2 Kaki Bukit Avenue 2, #02-32 Kaki Bukit Auto Hub, Singapore 417921

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate: \$11,635.68

Revised Amount

: \$5,850.00

Less Excess

. --

Nett Total

: \$5,850.00

Remarks

- (A) Survey was done on 13/04/2022
- (B) Re-survey was done on 14/04/2022
- (C) Re-survey after repair was done on 19/04/2022
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

Constant Appraiser Services

Vehicle No: SKX 8347R

Our ref: CAS/22-04/013

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by	Revised
		PARTS REPLACEMENT - LIST ITEMS	S	Workshop (\$)	Amount (\$)
1	1pc	Tailgate			
2	lpc	Tailgate emblem logo	Repair	2,182.29	-
3	2pcs	Taillamp @ \$647.24	Not Necessary	239.85	-
4	1pc	Rear bumper	N/S Broken	1,294.48	647.24
5	lpc	Rear bumper tow hook cover	Dented/Broken	1,638.01	1,638.01 1/2
6	1pc	Rear bumper reinforcement	Serviceable	93.72	-
7	lpc	Rear bumper center guard	Dented/Bent	754.65	754.65
8	1 pcs	Page house	Broken	126.66	126.66 754.70
9	2pcs		Broken	754.70	754.70
10		Rear bumper retainer @ \$377.35	Serviceable	754.70	-
11	lpc	Smart opening sensor	Damaged	104.00	104.00
12	lpc	Smart opening sensor holder	Broken	143.26	143.26
	lpc	Smart opening control unit	Damaged	1,100.88	1,100.88
13	4pcs	Rear parking sensor @ \$417.93 235	2 Damaged	1,671.72	835.86
14	1pc	Rear end panel	Repair	1,096.53	-
				11,955.45	6,105.26
		Less 5%		(597.77)	(305.26)
		PARTS REPLACEMENT – SPECIAL NETT ITEMS	Sub total	11,357.68	5,800.00
1	1pc	Tailgate glass sealant	Not Necessary	100.00	_
2	1 set	Rear bumper clip	Necessary	58.00	58.00 150
			Part total	11,515.68	5,858.00
		LABOUR & MISC. CHARGES		11,015.00	3,036.00
1		Labour to repair & replace damaged parts		700.00	500.00
2	1	To respray painting on accident portion		900.00	600.00 45
3	1	To remove, replace parking sensor		80.00	60.00
4		To check wiring		20.00	20,00
5	1	To diagnose & reset system after repair		420.00	260.00 X N
			Grand total	11,635.68	7,298.00
ecomme	ended cost	of lump sum repair	Oranic total	11,033.00	
To ito me	e-accident	condition)			5,850.00

Constant Appraiser Services

Vehicle No : SKX 8347R Our ref : CAS/22-04/013

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$5,850.00 on a contractual basis. Under normal circumstances, the repair period would be about 5 (Five) working days.

Yours faithfully,

Constant Appraiser Services

Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA