Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040 Tel/Fax: 6886 1106 Mobile: 9007 5234 Email: constant\_as@yahoo.com.sg RCB No. 53138015K

### **INVOICE**

To: Jolie Dion c/o Blk 2 Kaki Bukit Avenue 2 #02-32 Kaki Bukit Auto Hub Singapore 417921

Date

: 22/04/2022

Cly -

Invoice No

: IV22-04013/CAS

Particulars .	Amount
Fee For Services Rendered In Respect Of:  Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SKX 8347R (Inclusive Of Photographs And Transport Charges)  Our reference: CAS/22-04/013	\$711.00
Total	\$711.00

E. & O.E



Qualified Automobile Accident Damage Appraisers/Loss Adjusters Blk 2 Rivervale Link, #09-02 Singapore 545040 Tel/Fax: 6886 1106 Mobile: 9007 5234 Email: constant as@yahoo.com.sg

RCB No. 53138015K

### **Automobile Inspection Report**

To: Jolie Dion

c/o Blk 2 Kaki Bukit Avenue 2 #02-32 Kaki Bukit Auto Hub

Singapore 417921

Date

: 22/04/2022

Reference No : CAS/22-04/013

### **General Information**

Registration No.

: SKX 8347R

Accident Date

04/04/2022

### Particulars of Damaged Vehicle

Colour

Grey

Make & Model

: BMW 216D

**Engine Capacity** 

1496 cc

Pre-Accident Condition Good

Mileage (KM)

198255 : WBA2B32090V259765 Engine No. Steering

32139364B37C15A

Chassis No.

Registration Date 29/12/2015

Brake

: In Order : In Order

### Tyre Condition

Size

Make

Balance

R/H Front Tyre L/H Front Tyre

205/55R16

**BRIDGESTONE** 

90%

205/55R16

BRIDGESTONE

90%

R/H Rear Tyre

205/55R16

KUMHO

90%

L/H Rear Tyre

205/55R16

**KUMHO** 

90%

### Inspection

Repairer

Chng Brother Motor Services

Blk 2 Kaki Bukit Avenue 2, #02-32 Kaki Bukit Auto Hub, Singapore 417921

### Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$11.635.68

Revised Amount

: \$5,850.00

Less Excess

Nett Total

: \$5,850.00

### Remarks

- (A) Survey was done on 13/04/2022
- (B) Re-survey was done on 14/04/2022
- (C) Re-survey after repair was done on 19/04/2022
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Vehicle No: SKX 8347R

Our ref: CAS/22-04/013

### Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		PARTS REPLACEMENT – LIST ITEMS			
1	1pc	Tailgate	Repair	2,182.29	=
2	1pc	Tailgate emblem logo	Not Necessary	239.85	ž
3	2pcs	Taillamp @ \$647.24	N/S Broken	1,294.48	647.24
4	1pc	Rear bumper	Dented/Broken	1,638.01	1,638.01
5	1pc	Rear bumper tow hook cover	Serviceable	93.72	
6	1pc	Rear bumper reinforcement	Dented/Bent	754.65	754.65
7	1pc	Rear bumper center guard	Broken	126.66	126.66
8	2pcs	Rear bumper side holder @ \$377.35	Broken	754.70	754.70
9	2pcs	Rear bumper retainer @ \$377.35	Serviceable	754.70	Ģ.
10	1pc	Smart opening sensor	Damaged	104.00	104.00
11	1pc	Smart opening sensor holder	Broken	143.26	143.26
12	1pc	Smart opening control unit	Damaged	1,100.88	1,100.88
13	4pcs	Rear parking sensor @ \$417.93	2pcs Damaged	1,671.72	835.86
14	1pc	Rear end panel	Repair	1,096.53	(=
				11,955.45	6,105.26
		Less 5%		(597.77)	(305.26)
			Sub total	11,357.68	5,800.00
		PARTS REPLACEMENT – SPECIAL NETT ITEMS			
1	1pc	Tailgate glass sealant	Not Necessary	100.00	-
2	1 set	Rear bumper clip	Necessary	58.00	58.00
		_	Part total	11,515.68	5,858.00
		LABOUR & MISC. CHARGES			
1		Labour to repair & replace damaged parts		700.00	500.00
2		To respray painting on accident portion		900.00	600.00
3		To remove, replace parking sensor		80.00	60.00
4		To check wiring		20.00	20.00
5		To diagnose & reset system after repair		420.00	260.00
			Grand total	11,635.68	7,298.00
		t of lump sum repair t condition)			5,850.00

Vehicle No: SKX 8347R Our ref: CAS/22-04/013

### Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$5,850.00 on a contractual basis. Under normal circumstances, the repair period would be about 5 (Five) working days.

Yours faithfully,

Constant Appraiser Services

Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

**MSAAA** 

































































































