

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006795/GQY3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00009012101		
Claimant Vehicle No :	FBT4505E	Insured Vehicle No :	SLM3983H		
Date of Loss:	05/07/2022	Nature of Claim:	TP	Claim No:	SNM22D204844/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBT4505E		
Make & Model:	YAMAHA NMAX155, 155cc	Engine No:	HIDDEN
Reg. Date:	(Man. Year:)	Chassis No:	0
Colour:	Silver	Odometer:	5070 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	130/70-13
Front Left Side:	IRC 6 mm	Rear Left Side:	IRC 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,855.00	2,147.70	707.30	24.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	430.00	320.00	110.00	25.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	3,285.00	2,467.70	817.30	24.88

INSPECTION

Date of Assignment:	01/09/2022		
Date Inspected:	18/07/2022 Inspected At:	25 KAKI BUKIT ROAD 4, #01-28, SYNERGY @ KB	
Estimated Period of Repair:	2.0 days	Repairer:BIKES & TEA PTE L (HQ)	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 May 2023)	
Parts:	N/A	YAMAHA NMAX155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBT4505E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT LEVER	Cut	22.00 F	*22.00 FL
2	1		*RIGHT LEVER	Cut	22.00 F	*22.00 FL
3	1		*LEFT MIRROR	Cut	25.00 F	*25.00 FL
4	1		*RIGHT MIRROR	Cut	25.00 F	*25.00 FL
5	1		*LEFT BALANCER	Cut	10.00 F	*10.00 FL
6	1		*RIGHT BALANCER	Cut	10.00 F	*10.00 FL
7	1		*FRONT NO PLATE HOLDER	Cut	20.00 F	*20.00 FL
8	1		*COVERSET	Cut	450.00 F	*450.00 FL
9	1		*BLACK COVER (LEFT SIGNAL SIDE)	Cut	35.00 F	*35.00 FL
10	1		*BLACK COVER (RIGHT SIGNAL SIDE)	Cut	35.00 F	*35.00 FL
11	1		*LEFT FLOORBOARD	Cut	55.00 F	*55.00 FL
12	1		*RIGHT FLOORBOARD	Cut	55.00 F	*55.00 FL
13	1		*RIGHT SIDE BLACK COVER	Cut	80.00 F	*80.00 FL
14	1		*BACK WITH BASE PLATE	Cut	250.00 F	*250.00 FL
15	1		*REAR CARRIER	Cut	280.00 F	*280.00 FL
16	1		*TAIL LIGHT	Cracked	300.00 F	*300.00 FL
17	1		*AIRBOX	Cut	110.00 F	*110.00 FL
18	1		*REAR MUDGUARD	Cracked	65.00 F	*65.00 FL
19	1		*LICENSE PLATE LIGHT	Cracked	30.00 F	*30.00 FL
20	1		*REFLECTOR	Missing	12.00 F	*12.00 FL
21	1		*EXHAUST COVER	Cut	45.00 F	*45.00 FL
22	1		*RADIATOR COVER	Cut	32.00 F	*32.00 FL
23	1		*HANDLEBAR	Bent	105.00 F	*105.00 FL
24	2		*SUSPENSION	Not Necessary	500.00 F	*- FL
25	2		*NUMBER PLATE	Bent	60.00 FS	*60.00 FS
26	1		*MAIN STAND	Bent	150.00 FS	*150.00 FS
27	1		*SIDE STAND	Bent	72.00 FS	*72.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,855.00	2,355.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	207.30
Total Parts (\$\$)	2,855.00	2,147.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	250.00	200.00
2	FORK ALIGNMENT	New	180.00	120.00
Gross Labour Cost (S\$)			430.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >