

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

Insured Veh. SLU 8881T Veh. Inspected SFJ 418E	PRE-REPAIR INSPECTION REPORT							
TOWER SINGAPORE 048623 Code: SMO		SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO22006797/Kvy3e2		
Insured Veh. SLU 8881T Veh. Inspected SFJ 418E					Date:	25/07/2022		
Insured Veh. SLU 8881T Veh. Inspected SFJ 418E					Code:	SMO		
Policy No.	1.		Policy Particulars :- (THIRD PARTY CLAIM)					
Claim No. CMTD2202435/THE Excess (\$) 0.00		Insured Veh.	SLU 8881T	Veh. Inspected	t	SFJ 418E		
Assign From GRACE TEO Assign Date 18/07/2022		Policy No.		Coverage (\$)		0.00		
Nake & Model		Claim No.	CMTD2202435/THE	Excess (\$)		0.00		
Make & Model		Assign From	GRACE TEO	Assign Date		18/07/2022		
Engine No. HIDDEN Year of Reg. 2022 Chassis No. GK82202424 Colour METALLIC GREY Odometer 9572 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres	2.	Vehicle Particulars & Condition						
Chassis No. GK82202424 Colour METALLIC GREY Odometer 9572 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance		Make & Model	HONDA SHUTTLE (A)	c.c		1496		
Odometer 9572 KM Steering IN ORDER		Engine No.	HIDDEN	Year of Reg.		2022		
Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance R/H Front Tyre 185/60 R15 YOKOHAMA 9 mm L/H Front Tyre 185/60 R15 YOKOHAMA 9 mm R/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm L/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm L/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500 5b. Estimate Days of Repair		Chassis No.	GK82202424	Colour		METALLIC GREY		
General GOOD 3. Conditions of Tyres Size Make Balance		Odometer	9572 KM	Steering		IN ORDER		
Conditions of Tyres Size		Brakes	IN ORDER	Modification		SPORTS RIM		
R/H Front Tyre 185/60 R15 YOKOHAMA 9 mm L/H Front Tyre 185/60 R15 YOKOHAMA 9 mm R/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm L/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 Sa. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500		General	GOOD					
R/H Front Tyre	3. Conditions of Tyres							
L/H Front Tyre 185/60 R15 YOKOHAMA 9 mm R/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm L/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm L/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. 5. General Information Accident Date 15/07/2022 Inspect Date / Time 19/07/2022 (03:15 PM) Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500			Size	Make		Balance		
R/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm L/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. General Information Accident Date 15/07/2022 Inspect Date / Time 19/07/2022 (03:15 PM) Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500		R/H Front Tyre	185/60 R15	YOKOHAMA		9 mm		
L/H Rear Tyre 185/60 R15 YOKOHAMA 9 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. 5. General Information Accident Date 15/07/2022 Inspect Date / Time 19/07/2022 (03:15 PM) Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500		L/H Front Tyre	185/60 R15	YOKOHAMA		9 mm		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. General Information Accident Date 15/07/2022 Inspect Date / Time 19/07/2022 (03:15 PM) Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500		R/H Rear Tyre	185/60 R15	YOKOHAMA		9 mm		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. General Information Accident Date 15/07/2022 Inspect Date / Time 19/07/2022 (03:15 PM) Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500		L/H Rear Tyre	185/60 R15	YOKOHAMA		9 mm		
5. General Information Accident Date 15/07/2022 Inspect Date / Time 19/07/2022 (03:15 PM) Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500	4.	Description of Damages						
Accident Date 15/07/2022 Inspect Date / Time 19/07/2022 (03:15 PM) Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500		THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTIO			l.			
Survey held at 8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500 5b. Estimate Days of Repair	5.	General Information						
71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500 5b. Estimate Days of Repair		Accident Date	15/07/2022	Inspect Date /	Time	19/07/2022 (03:15 PM)		
SINGAPORE 737743 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500 5b. Estimate Days of Repair		Survey held at	urvey held at 8 PARAGON PTE LTD					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500 Estimate Days of Repair								
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500 Estimate Days of Repair	5a.							
		B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL	B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					
ECTIMATED MODIMAL DEDICE FOR DEDAID.	5b.		Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days		ESTIMATED NOR						

Report Ref No. CS3/SMO22006797/Kvy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser