

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006799/UCY3Q2**Date:** 29/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00047222205

Claimant Vehicle No : SLG7863B **Insured Vehicle No :** SLL8198E

Date of Loss: 13/07/2022 Nature of Claim: TP Claim No: SNM22D204846/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG7863B**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4033852

Reg. Date: 13/10/2016 (Man. Year: 2016) Chassis No: RU11113849

Colour: White Odometer: 100626 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,895.20	3,641.36	10,253.84	73.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	1,770.00	2,400.00	57.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,065.20	5,411.36	12,653.84	70.05
Approved Total (Overridden) (\$\$)		4,300.00		
Nett Amount (\$\$)	18,065.20	4,300.00	13,765.20	76.20

INSPECTION

Date of Assignment: 23/08/2022

Date Inspected: 19/07/2022 Inspected At: SPEEDWERKZ PTE LTD (HQ)
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre
Singapore 147807

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Aug 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG7863B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,355.00 FL	*997.20 FL
2	4		*TAILGATE GLASS MOULDING	Necessary	240.00 FL	*110.20 FL
3	1		*TAILGATE LOGO	Not Necessary	58.00 FL	*- FL
4	1		*TAILGATE EMBLEM -VEZEL	Necessary	67.00 FL	*65.80 FL
5	1		*TAILGATE INNER LAMP LH	Cracked	395.00 FL	*295.20 FL
6	1		*TAILGATE INNER LAMP RH	Not Necessary	395.00 FL	*- FL
7	1		*TAILGATE OUTER GARNISH	Not Necessary	325.00 FL	*- FL
8	1		*TAILGATE LOCK	Bent	275.00 FL	*275.00 FL
9	1		*TAILGATE LOCK STRIKER	Not Necessary	45.00 FL	*- FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	155.00 FL	*155.00 FL
11	1		*TAILGATE DAMPER LH	Not Necessary	255.00 FL	*- FL
12	1		*TAILGATE DAMPER RH	Not Necessary	255.00 FL	*- FL
13	1		*TAILGATE INNER PULL COVER	Not Necessary	25.00 FL	*- FL
14	1		*TAILGATE INNER TRIM	Torn	314.00 FL	*314.00 FL
15	1		*TAILGATE WIPER MOTOR	Not Necessary	301.00 FL	*- FL
16	2		*TAILGATE HINGE	Not Necessary	150.00 FL	*- FL
17	1		*REAR BUMPER	Dented	751.00 FL	*751.00 FL
18	2		*REAR BUMPER SIDE RETAINER	Not Necessary	76.00 FL	*- FL
19	1		*REAR BUMPER REFLECTOR LH	Cracked	89.00 FL	*89.00 FL
20	1		*REAR BUMPER REFLECTOR RH	Not Necessary	89.00 FL	*- FL
21	1		*REAR BUMPER UNDERCOVER	Deformed / Twisted	310.00 FL	*310.00 FL
22	1		*REAR LOCK SENSOR	Not Necessary	280.00 FL	*- FL
23	1		*REAR CORNER BUMPER LH	Deformed	225.00 FL	*151.00 FL
24	1		*REAR CORNER BUMPER RH	Not Necessary	225.00 FL	*- FL
25	1		*REAR FENDER SIDE GARNISH LH	Not Necessary	255.00 FL	*- FL
26	1		*REAR FENDER SIDE GARNISH RH	Not Necessary	255.00 FL	*- FL
27	1		*REAR TAILLAMP LH	Cracked	520.00 FL	*460.80 FL
28	1		*REAR TAILLAMP RH	Not Necessary	520.00 FL	*- FL
29	1		*END PANEL	Repair	585.00 FL	*- FL
30	1		*END PANEL TOP GARNISH	Twisted	165.00 FL	*165.00 FL
31	1		*SPARE TYRE TOP BOARD	Not Necessary	389.00 FL	*- FL
32	1		*FLOOR PANEL COMPARTMENT	Not Necessary	901.00 FL	*- FL
33	1		*TOOL SPONGE	Not Necessary	155.00 FL	*- FL
34	1		*REAR EXHAUST SILENCER	Not Necessary	748.00 FL	*- FL
35	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	68.00 FL	*- FL
36	2		*REAR EXHAUST MOUNTING	Not Necessary	70.00 FL	*- FL
37	1		*REAR FENDER INNER TRIM LH	Not Necessary	389.00 FL	*- FL
38	1		*REAR FENDER INNER TRIM RH	Not Necessary	389.00 FL	*- FL
39	1		*REAR FENDER LH	Not Necessary	1,431.00 FL	*- FL
40	1		*REAR FENDER RH	Not Necessary	1,431.00 FL	*- FL
41	1		*BONNET	Not Necessary	898.00 FL	*- FL
42	1		*BONNET HINGE LH	Not Necessary	55.00 FL	*- FL
43	1		*BONNET HINGE RH	Not Necessary	55.00 FL	*- FL
44	1		*BONNET INSULATOR	Not Necessary	135.00 FL	*- FL
45	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
46	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

8/29/22, 2:15 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR TAILGATE INNER TRIM CLIP	Necessary	40.00 FS	*40.00 FS
48	1		*SET REAR REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
49	1		*JOINT SEALANT END PANEL	Not Necessary	150.00 FS	*- FS
50	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
51	1		*FLOOR INSULATOR	Not Necessary	150.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					17,109.00	4,469.20
- List Item Discount on L Items 20.00/20.00% (S\$)					3,213.80	827.84
Total Parts (S\$)					13,895.20	3,641.36
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	120.00	20.00
2	REMOVE ,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	80.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	50.00
4	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
6	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
7	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,500.00	600.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	800.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	40.00
Gross Labour Cost (\$\$)			4,170.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >