

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22006801/AYA3Q2**Date:** 14/03/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_01
Claimant Vehicle No : SMT6358U **Insured Vehicle No :** SMZ4822C
 Date of Loss: 15/07/2022 Nature of Claim: TP Claim No: MFL2022D0003748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT6358U**
 Make & Model: TOYOTA LAND CRUISER, PRADO 2.7 TX (A) Engine No: 2TR2047029
 Reg. Date: 22/10/2018 (Man. Year: 2018) Chassis No: TRJ1500088312
 Colour: White Odometer: 98261 km
 Engine Capacity: 2693 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/65 R17 Rear Tyre Size: 265/65 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,236.77	8,094.97	13,141.80	61.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,670.00	1,990.00	3,680.00	64.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,906.77	10,084.97	16,821.80	62.52
Approved Total (Overridden) (S\$)		7,800.00		
(S\$)	26,906.77	7,800.00	19,106.77	71.01
+ GST 7.00/7.00% (S\$)	1,883.47	546.00	1,337.47	71.01
Nett Amount (S\$)	28,790.24	8,346.00	20,444.24	71.01
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,053.45		

INSPECTION

Date of Assignment: 18/07/2022
 Date Inspected: 19/07/2022 Inspected At: Xin Hua Workshop Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01
 Singapore 415933
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2022)
Parts:	192	TOYOTA LAND CRUISER PRADO 2.7 TX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT6358U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Dented	2,458.90 FL	*1,880.00 FL
2	1	*TAILGATE LOGO	Necessary	98.70 FL	*98.70 FL
3	1	*TAILGATE EMBLEM TX	Necessary	95.60 FL	*95.60 FL
4	1	*TAILGATE OUTER GARNISH	Cracked	1,485.20 FL	*885.00 FL
5	1	*TAILGATE OUTER GARNISH TOP CHROME TRIM	Not Necessary	508.60 FL	*- FL
6	2	*TAILGATE HINGE	Not Necessary	340.00 FL	*- FL
7	2	*TAILGATE NUMBER PLATE LAMPS	Not Necessary	197.40 FL	*- FL
8	1	*TAILGATE LOCK	Not Necessary	485.90 FL	*- FL
9	1	*TAILGATE LOCK CATCH	Not Necessary	38.00 FL	*- FL
10	1	*TAILGATE INNER BOARD	Not Necessary	725.80 FL	*- FL
11	1	*TAILGATE WEATHERSTRIP	Cut	398.50 FL	*398.50 FL
12	2	*TAILGATE STOPPER	Not Necessary	80.00 FL	*- FL
13	1	*TAILGATE HYDRAULIC DAMPER	Not Necessary	425.90 FL	*- FL
14	1	*TAILGATE WINDSCREEN GLASS C/W MOULDING	Necessary	1,410.00 FL	*245.00 FL
15	1	*SPARE TYRE BRACKET	Not Necessary	580.00 FL	*- FL
16	1	*REAR BUMPER	Deformed	2,452.30 FL	*1,560.00 FL
17	1	*REAR BUMPER PROTECTOR	Deformed	458.20 FL	*458.20 FL
18	1	*REAR BUMPER SENSORS (6 PCS)	Damaged (2 PCS ONLY)	1,737.60 FL	*579.20 FL
19	6	*REAR BUMPER SENSORS HOLDERS	Necessary	293.40 FL	*150.00 FL
20	3	*REAR BUMPER CENTER UPPER BRACKET	Not Necessary	295.80 FL	*- FL
21	2	*REAR BUMPER RETAINER	Not Necessary	371.80 FL	*- FL
22	2	*REAR BUMPER REFLECTORS	Cracked	771.20 FL	*370.00 FL
23	1	*REAR BUMPER LOWER BRACKET	Not Necessary	305.80 FL	*- FL
24	1	*REAR BUMPER REINFORCEMENT	Dented	785.90 FL	*785.90 FL
25	1	*REAR BUMPER TOWING COVER	Not Necessary	59.30 FL	*- FL
26	1	*REAR END PANEL (OUTER)	Repair	845.60 FL	*- FL
27	1	*REAR END PANEL TOP GARNISH	Deformed	298.50 FL	*298.50 FL
28	1	*TAILLAMPS	N/S Cracked	1,651.80 FL	*520.00 FL
29	2	*TAILLAMPS PANEL	Not Necessary	491.80 FL	*- FL
30	2	*TAILLAMPS INNER SEALER	Not Necessary	80.00 FL	*- FL
31	2	*TAILLAMPS LOWER BRACKET	Not Necessary	210.60 FL	*- FL
32	1	*REAR FLOOR PANEL	Not Necessary	950.00 FL	*- FL
33	1	*REAR FLOOR MAT	Not Necessary	693.00 FL	*- FL
34	2	*REAR FENDER MUDFLAP	Not Necessary	139.60 FL	*- FL
35	1	*REAR SILENCER BOX	Bent	1,698.50 FL	*1,450.00 FL
36	2	*REAR SILENCER BOX MOUNTING	Not Necessary	137.80 FL	*- FL
37	1	*REAR BUMPER TOP COVER (BLACK)	Deformed	298.70 FL	*298.70 FL
38	1	*REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
39	1	*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
40	1	*REAR BUMPER RECOVERY LED LAMP	Damaged	550.00 FS	*300.00 FS
41	1	*SET TAILGATE INNER BOARD CLIP	Not Necessary	50.00 FS	*- FS
42	1	*TAILGATE WINDSCREEN INNER SEAL	Necessary	100.00 FS	*50.00 FS
43	1	*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
44	1	*TAILGATE NAGANO TOYOTA STICKER	Necessary	120.00 FS	*80.00 FS
45	2	*SET REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

3/14/23, 2:48 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	2		*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS
47	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
48	1		*SET REAR FLOOR PANEL INSULATOR PADS	Not Necessary	350.00 FS	*- FS
49	1		*END PANEL SEALANT	Not Necessary	150.00 FS	*- FS
50	1		*REAR SPARE TYRE RIM	Not Necessary	900.00 FS	*- FS
51	1		*REAR SPARE TYRE	Not Necessary	350.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					27,325.70	10,613.30
- List Item Discount on L Items 25.00/25.00% (S\$)					6,088.93	2,518.33
Total Parts (S\$)					21,236.77	8,094.97
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	2,200.00	700.00
2	TO SPRAY PAINT AFFECTED AREA (PEARL WHITE)	New	2,000.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK ON TAILAMPS	New	120.00	30.00
5	REMOVE/REPLACE REAR SENSOR	New	120.00	60.00
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	0.00
8	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
9	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	REMOVE AND REPLACE SILENCER BOX	New	150.00	80.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,670.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >