



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2193Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BROKEN	1,075.00	1,075.00
10	REAR BUMPER CLIPS @\$4.00	NECESSARY	40.00	30.00
2	REAR BUMPER TOW COVER @\$55.00	NOT NECESSARY	110.00	-
2	REAR BUMPER REFLECTOR @\$115.00	NOT NECESSARY	230.00	-
1	REAR BUMPER INNER BRACKET	NOT NECESSARY	45.00	-
1	REAR REINFORCEMENT	NOT NECESSARY	545.00	-
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-409.00	-221.00
			1,636.00	884.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACED REAR REVERSE SENSOR.		100.00	30.00
	TO KNOCKING AND PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	400.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		600.00	400.00
			1,300.00	830.00
GRAND TOTAL			3,216.00	1,914.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,550.00

Report Ref No. CS/AGI22006802/Ecy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.