



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 8177U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	BROKEN	185.00	166.00
2	FRONT SIDE FORK ASSY	SERVICEABLE	2,040.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	385.00	-
1	FRONT SPORT RIM	NOT NECESSARY	350.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	220.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	52.00	-
1	WINDSHIELD	SCRATCHED	245.00	245.00
1	HEADLAMP ASSY -LH	SCRATCHED	844.00	750.00
1	SIDE MIRROR ASSY -LH	CUT	178.00	178.00
1	HANDLE BAR	BENT	188.00	188.00
1	HANDLE BAR BALANCER -LH	CUT	80.00	40.00
1	CLUTCH LEVER	CUT	78.00	78.00
1	FRONT SIGNAL -LH	SERVICEABLE	225.00	-
1	CENTRE INNER PANEL HANDLE (CRACKED)	NOT CONSISTENT WITH THE IMPACT	150.00	-
1	FOOTSTEP PANEL -LH	CUT	168.00	168.00
1	REAR FOOTREST -LH	CUT	55.00	55.00
1	DROVE BELT COVER }	CUT	345.00	345.00
1	DROVE BELT OUTER GARNISH }		215.00	-
1	AIR FILTER BOX COVER	CUT	250.00	250.00
1	MAIN STAND	TO REPAIR SEE LABOUR	145.00	-
1	SIDE STAND	TO REPAIR SEE LABOUR	95.00	-
1	REAR MUDGUARD	NOT NECESSARY	148.00	-
1	SET FAIRING COVER	CUT/DAMAGED	1,350.00	900.00
	LESS 10% DISCOUNT		-799.10	-336.30
			7,191.90	3,026.70
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
1	REAR BOX (SN)	CUT	680.00	300.00

Report Ref No. CS/SMO22006806/Uqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX BRACKET (SN)	NOT NECESSARY	150.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	185.00	-
1	"K-XCT" EMBLEM (SN)	NECESSARY	55.00	55.00
			1,184.00	355.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.	NOT NECESSARY	50.00	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF MAIN STAND AND SIDE STAND.		480.00	300.00
	TO RESPRAY PAINTING.		1,200.00	380.00
			1,810.00	680.00
GRAND TOTAL			10,185.90	4,061.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/SMO22006806/Uqy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.