

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22006808/EQY3E2

**Date:** 10/08/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00093112100	
<b>Claimant Vehicle No :</b>	SLM2527Z	<b>Insured Vehicle No :</b>	SLU480U	
Date of Loss:	05/11/2021	Nature of Claim:	TP	Claim No: SNM21D206608/CO2/CHEESC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLM2527Z</b>		Engine No:	K9KG657R003743
Make & Model:	RENAULT MEGANE, 1.5 D Sedan DCI AT EU6 (M)		Chassis No:	VF1RFB00656852731
Reg. Date:	24/03/2017 (Man. Year: 2016)		Odometer:	106284 km
Colour:	White			
Engine Capacity:	1461 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,923.30	743.55	4,179.75	84.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,950.00	1,750.00	37.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,623.30</b>	<b>3,693.55</b>	<b>5,929.75</b>	<b>61.62</b>
<b>+ GST 7.00/7.00% (S\$)</b>	673.63	258.55	415.08	61.62
<b>Nett Amount (S\$)</b>	<b>10,296.93</b>	<b>3,952.10</b>	<b>6,344.83</b>	<b>61.62</b>

### INSPECTION

Date of Assignment:	02/08/2022		
Date Inspected:	18/07/2022	Inspected At:	Wearnes Automotive Pte Ltd 45 Leng Kee Road Singapore 159103
Estimated Period of Repair:	4.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2022)
Parts:	143	RENAULT MEGANE 1.5 D Sedan DCI AT EU6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM2527Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE WITH HOLDER	Cut	60.00 FS	*60.00 FS
2	1		*BUMPER REAR M4S	Repair	950.70 FS	*- FS
3	1		*BUMPER REAR OUTER SI	Not Necessary	220.00 FS	*- FS
4	1		*BUMPER REAR INNER SI	Not Necessary	242.30 FS	*- FS
5	1		*BOOT OUTER PANEL WIT	Repair	990.50 FS	*- FS
6	1		*R908922947R/EMBLE M	Necessary	148.90 FS	*134.01 FS
7	1		*LOGO REAR M4S	Necessary	181.30 FS	*163.17 FS
8	1		*ADHESIVE SEALER FL2	Not Necessary	745.10 FS	*- FS
9	1		*BUMPER PAD LOWER M4S	Cut	429.30 FS	*386.37 FS
10	1		*BODY PANEL SEALANT X	Not Necessary	955.20 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,923.30	743.55
--------------------	----------	--------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER, REAR LOWER BUMPER	New	1,650.00	550.00
2	TO BLEND AND SPRAY PAINT ON UPPER BOOTLID, OUTER BOOTLID, REAR BUMPER, BRACKETS, CLIPS, ETC	New	2,600.00	1,950.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	450.00	450.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,700.00</b>	<b>2,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >