



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 7167Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	MTG CRACKED	866.80	866.80
1	FRONT BUMPER RH SIDE RETAINER (CONSISTENT)	DISTORTED	19.70	19.70
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT BUMPER INNER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	593.40	-
1	RH HEADLAMP (CONSISTENT)	SERVICEABLE	1,070.50	-
1	FRONT RH SIDE MIRROR COVER (CONSISTENT)	DENTED	111.00	111.00
1	FRONT RH SIDE MIRROR BODY (CONSISTENT)	MTG DISTORTED	396.90	396.90
1	FRONT RH FENDER (CONSISTENT)	BENT	350.60	350.60
2	FRONT FENDER UNDER SHIELD (CONSISTENT)	DISTORTED	104.40	104.40
1	SET FRONT FENDER UNDER SHIELD CLIPS (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT RH DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,200.94	-
1	FRONT RH DOOR WEATHERSTRIP (CONSISTENT)	SERVICEABLE	118.90	-
1	FRONT RH SPORT RIM (CONSISTENT)	CUT / DENTED	432.60	432.60
1	FRONT RH SHOCK ABSORBER (CONSISTENT)	BENT	301.40	301.40
1	FRONT RH LOWER ARM (CONSISTENT)	SERVICEABLE	509.00	-
1	FRONT RH KNUCKLE ARM (CONSISTENT)	BENT	402.60	402.60
1	FRONT RH WHEEL HUB & BEARING (CONSISTENT)	NECESSARY	568.80	568.80
1	FRONT STABILIZER BAR (CONSISTENT)	SERVICEABLE	322.00	-
	LESS 20% DISCOUNT		-1,489.91	-726.96
			5,959.63	2,907.84
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT RH TYRE (SN) (CONSISTENT)	SERVICEABLE	240.00	-
			240.00	-
<b><u>LABOUR</u></b>				
	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING /WELDING AND REPLACEMENT OF DAMAGES.INCLUSIVE OF THE REPAIR OF FRONT BUMPER INNER REINFORCEMENT AND FRONT RH DOOR .		1,000.00	500.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING CHARGES.	NOT NECESSARY	1,000.00	600.00
	TO CHECK WIRINGS AND LIGHTINGS .		50.00	20.00
	TO REMOVE ,REFIT FRONT RH DOOR FITTINGS.		80.00	-
	TO REMOVE,REFIT FRONT RH UNDER CARRIAGES.		280.00	160.00
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.		80.00	60.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.		100.00	30.00
			2,590.00	1,370.00
GRAND TOTAL			8,789.63	4,277.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CC4/ASM22006809/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.