

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22006812/APA3Q2**Date:** 07/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800049974-04
Claimant Vehicle No :	SCJ93T	Insured Vehicle No :	SLD8865E
Date of Loss:	18/07/2022	Nature of Claim:	TP
		Claim No:	4473595731SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCJ93T	Engine No:	DKY015967
Make & Model:	AUDI A6, 2.0 TFSI (A)	Chassis No:	WAUZZZF28MN098212
Reg. Date:	09/09/2021 (Man. Year: 2021)	Odometer:	17788 km
Colour:	Green		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R20	Rear Tyre Size:	255/40 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,833.92	5,268.40	6,565.52	55.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,012.00	6,132.00	6,880.00	52.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,845.92	11,400.40	13,445.52	54.12
+ GST 8.00/8.00% (S\$)	1,987.67	912.03	1,075.64	54.12
Nett Amount (S\$)	26,833.59	12,312.43	14,521.16	54.12
+ Car Rental (8.0 x S\$150.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,514.43		

INSPECTION

Date of Assignment:	21/07/2022		
Date Inspected:	21/07/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -RH	Distorted	1,649.00 FS	*1,319.20 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	44.00 FS	*- FS
3	1		*FRONT FENDER BRACE -RH	Not Necessary	137.00 FS	*- FS
4	1		*FRONT FENDER BRACKET -RH UPPER	Not Necessary	49.00 FS	*- FS
5	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	60.00 FS	*- FS
6	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	299.00 FS	*- FS
7	1		*FRONT FENDER STONE CHIP GUARD -RH	Cut	57.00 FS	*45.28 FS
8	1		*FRONT FENDER BRACKET TRIM -RH	Not Necessary	45.00 FS	*- FS
9	1		*FRONT DOOR -RH	Dented	4,489.00 FS	*3,591.20 FS
10	1		*FRONT OUTER DOOR SEAL -RH	Necessary	191.00 FS	*152.80 FS
11	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	379.00 FS	*- FS
12	1		*FRONT DOOR CATCH -RH	Not Necessary	134.00 FS	*- FS
13	1		*FRONT EXTERIOR MIRROR MOUNTING -RH	Not Necessary	3,069.00 FS	*- FS
14	1		*FRONT MIRROR CAP RH	Repair	348.00 FS	*- FS
15	1		*FRONT WINDOW SLOT SEAL TRIM STRIP -RH OUTER	Not Necessary	224.00 FS	*- FS
16	2		*FRONT DOOR HINGE -RH UPPER /LOWER (NPA)	Not Necessary	0.00 FS	*- FS
17	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
18	1		*RHS FPONT RIM (NPA)	Not Necessary	0.00 FS	*- FS
19	1		*RHS REAR RIM (NPA)	Repair	0.00 FS	*- FS
20	1		*SET ATTACHMENT PARTS	Necessary	108.80 FS	*108.80 FS
21	1		*SET ADHESIVE TAPES	Necessary	51.12 FS	*51.12 FS
					Total Parts (S\$)	
					11,833.92	5,268.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	400.00	280.00
3	TO DISMANTLE AND REINSTALL FRONT BUMPER .TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR.TO REPAIR RHS REAR DOOR AND RHS REAR FENDER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	4,000.00	1,500.00
4	TO RESPRAY RHS FRONT FENDER ,RHS FRONT DOOR ,DOOR HINGES ,RHS WING MIRROR COVER ,DOOR HANDLE ,RHS REAR DOOR AND RHS REAR FENDER	New	4,500.00	2,350.00
5	TO RENEW RHS FRONT RIM AND RHS REAR RIM .TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	560.00	280.00
6	TO CARRY OUT CALIBRATION FOR RHS WING MIRROR 360 CAMERA	New	480.00	480.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REMOVE AND REINSTALL RHS SILL PANEL TRIM	New	1,200.00	500.00
9	TO RESPRAY RHS SILL PANEL TRIM	New	1,200.00	550.00
Gross Labour Cost (S\$)			13,012.00	6,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >