

VEHICLE DAMAGE INSPECTION REPORT

Tokio Marine Insurance Singapore Ltd
20 McCallum Street, #09-01 Tokio Marine Centre
Singapore 069046

Our File No: M2201275
Date: 13/05/2022

REFERENCE

Insured/Claimant:	TENG MOI ENG	Policy No:	MU008845		
Date of Loss:	16/03/2022	Nature of Claim:	OD	Claim No:	M2201275

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK6006G		Engine No:	2ARH923764
Make & Model:	TOYOTA VELLFIRE, 2.5 Z G CVT (A)		Chassis No:	AGH300128878
Reg. Date:	02/08/2017 (Man. Year: 2017)		Odometer:	84394 km
Colour:	Black			
Engine Capacity:	2493 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Bluearth 10 mm	Rear Left Side:	Bluearth 10 mm
Front Right Side:	Bluearth 10 mm	Rear Right Side:	Bluearth 10 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,019.00	5,203.00	2,816.00	35.12
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,210.00	690.00	520.00	42.98
Paintwork Labour	880.00	500.00	380.00	43.18
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,120.00	6,404.00	3,716.00	36.72
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	8,620.00	4,904.00	3,716.00	43.11
+ GST 7.00/7.00% (S\$)	603.40	343.28	260.12	43.11
Nett Amount (S\$)	9,223.40	5,247.28	3,976.12	43.11

INSPECTION

Date of Assignment:	17/03/2022	Present Location:	OD - SIN MING - LAWRENCE SURVEYED TODAY - 17.03.22(BW)
Date Inspected:	17/03/2022	Inspected At:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days		

Adjuster: Koon Shern Lawrence

Manager: Betty Wong

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2022)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.5 Z G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Tokio Marine Insurance Singapore Ltd/SKK6006G/13/05/2022 08:41	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front LH headlamp	Cut	1,900.00 F	*1,900.00 F
2	1		*Front LH headlamp cover	Serviceable	60.00 F	Repair
3	1		*Front LH headlamp top panel	Serviceable	200.00 F	Reuse
4	1		*Front grille assy	Cracked	720.00 F	*720.00 F
5	1		*Front no. plate garnish	Cut	140.00 F	*140.00 F
6	1		*Front bumper	Torn	370.00 F	*370.00 F
7	1		*Front bumper parking sensor @ \$170.00	Malfunction	340.00 F	*170.00 F
8	1		*Front bumper LH fog lamp	Serviceable	140.00 F	Reuse
9	1		*Front bumper LH fog lamp cover	Scratched	130.00 F	*130.00 F
10	1		*Front bumper centre lower grille	Serviceable	110.00 F	Reuse
11	1		*Front bumper LH side retainer	Necessary	40.00 F	*40.00 F
12	1		*Front bumper sponge	Cracked	60.00 F	*60.00 F
13	1		*Front bumper reinforcement	Serviceable	220.00 F	Reuse
14	10		*Front bumper clips @ \$2.00	Necessary	20.00 F	*20.00 F
15	1		*Wiper tank	Serviceable	60.00 F	Reuse
16	1		*Front LH fender	Dented	580.00 F	*580.00 F
17	1		*Front LH fender inner shield	Serviceable	140.00 F	Reuse
18	10		*Front LH fender inner shield clips @ \$2.00	Necessary	20.00 F	*20.00 F
19	1		*Front LH wheel bearing	Serviceable	360.00 F	Reuse
20	1		*Front LH wheel sport rim	Serviceable	1,100.00 F	Reuse

Supplementary #1

21	1		*Front LH headlamp lower bracket	Cracked	60.00 F	*60.00 F
22	1		*Front LH headlamp ECU	Malfunction	520.00 F	*520.00 F

F=Franchise part.

Sub Total (\$)	7,290.00	4,730.00
+ Margin on L,N Items 10.00/10.00% (\$)	729.00	473.00
Total Parts (\$)	8,019.00	5,203.00

Tokio Marine Insurance Singapore Ltd/SKK6006G/13/05/2022 08:41. Not valid without Reference section.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray painting	New	880.00	500.00
<u>Labour Items</u>				
2	To check wheel alignment	New	150.00	0.00
3	To reset headlamp system	New	280.00	150.00
4	To repair damages	New	780.00	540.00
Gross Labour Cost (S\$)			2,090.00	1,190.00

Tokio Marine Insurance Singapore Ltd/SKK6006G/13/05/2022 08:41. Not valid without Reference section.

< END OF ESTIMATES >