

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22006815/APA3Q2**Date:** 14/12/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0002486
Claimant Vehicle No :	SMN4911S	Insured Vehicle No :	SDT5995T
Date of Loss:	17/07/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0003865

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN4911S	Engine No:	L15Z12712413
Make & Model:	HONDA CITY, 1.5 SV CVT (A)	Chassis No:	MRHGM6660GP000228
Reg. Date:	14/03/2016 (Man. Year: 2015)	Odometer:	108307 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Grenlander 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,731.70	3,050.40	5,681.30	65.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,600.00	610.00	27.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,941.70	4,650.40	6,291.30	57.50
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	10,941.70	3,700.00	7,241.70	66.18
+ GST 7.00/7.00% (S\$)	765.92	259.00	506.92	66.18
Nett Amount (S\$)	11,707.62	3,959.00	7,748.62	66.18
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,386.45		

INSPECTION

Date of Assignment:	19/07/2022	Green Forest Automobile Pte Ltd (Kaki Bukit)
Date Inspected:	19/07/2022 Inspected At:	8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2022)
Parts: 143	HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMN4911S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,077.00 F	*685.10 FL
2	2		*REAR BOOT LID HINGES	Not Necessary	316.00 F	*- FL
3	1		*REAR BOOT LID CITY LOGO	Necessary	40.00 F	*40.00 FL
4	1		*REAR BOOT LID RH LOGO	Necessary	48.00 F	*48.00 FL
5	1		*REAR BOOT LID EMBLE LOGO	Necessary	65.00 F	*65.00 FL
6	1		*REAR BOOT LID CENTER MOULDING	Not Necessary	215.00 F	*- FL
7	6		*REAR BOOT LID CENTER MOULDING CLIPS	Not Necessary	39.00 F	*- FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	85.40 F	*- FL
10	1		*REAR BOOT LID INNER LOCK	Damaged	255.00 F	*255.00 FL
11	1		*REAR BOOT LID INNER RUBBER	Cut	235.00 F	*235.00 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	588.00 F	*- FL
13	2		*REAR BOOT LID SIDE REFLECTOR	Cracked	710.00 F	*333.00 FL
14	1		*REAR BOOT LID WINDSCREEN SEAL	Not Necessary	136.20 F	*- FL
15	2		*REAR TAIL LAMP	Cut	916.00 F	*450.00 FL
16	1		*REAR BUMPER	Deformed	950.00 F	*464.00 FL
17	2		*REAR BUMPER SIDE BRACKET	Necessary	310.00 F	*70.00 FL
18	8		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
19	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
20	1		*REAR BUMPER REINFORCEMENT	Not Necessary	588.00 F	*- FL
21	1		*REAR BUMPER TOWING COVER	Not Necessary	68.00 F	*- FL
22	1		*SPARE TYRE PANEL TOP BOARD	Torn	170.00 F	*170.00 FL
23	1		*REAR END PANEL	Dented	492.90 F	*492.90 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	215.00 F	*215.00 FL
25	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	772.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,731.70	3,763.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	712.60
Total Parts (\$\$)	8,731.70	3,050.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
2	REMOVE /REFIX REAR WINDSCREEN	New	120.00	0.00
3	GUM	New	50.00	0.00
4	TO REMOVE & REFIX CUSHION	New	120.00	60.00
5	TO CHECK WIRING	New	80.00	30.00
6	TUFF KOTE	New	120.00	60.00
7	PANEL BEATING	New	800.00	700.00
8	SPRAY PAINTING	New	800.00	700.00
Gross Labour Cost (S\$)			2,210.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >