

### OH APPRAISAL SERVICES

BLK 34,#02-309,TOA PAYOH,LORONG 5

SINGAPORE (310034)

Mobile : 97982959 Fax : 63975857 email : oh3434@yahoo.com.sg

### VEHICLE DAMAGE INSPECTION REPORT

Mr. Tan Kian Beng (Chen JianMiing)  
Blk 151 Rivervale Crescent  
#06-92  
Singapore 540151

Our Ref : SLM4044L/TP5050  
Date : 02 September 2022

#### REFERENCES

Claim Type	: Third Party	Date of Accident	: 15 July 2022
Vehicle No.	: SLM4044L	Date of Assignment	: 16 July 2022
Make	: Toyota	Date of Inspection	: 16 July 2022
Model	: Sienta	Date of Re-inspn.	: 20 July 2022
Reg. Date	: 2008	Chassis No	: MHFZ28H3500029531
Color	: Brown	Engine No	: Blocked
Odometer	: 140946 km		

#### TYRE CONDITION

	<u>Front near side</u>	<u>Front off side</u>	<u>Rear near side</u>	<u>Rear off side</u>
Make	Yokohama	Yokohama	Yokohama	Yokohama
Size	195/50 R16	195/50 R16	195/50 R16	195/50 R16
Thread Balance	5 mm	5 mm	6 mm	6 mm

#### GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at Rear portion

#### INSPECTION AND ADJUSTMENT

Original Quotation : \$21,383.83 Revised Assessment \$11,150.00 Lump sum

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately  
( 9 ) days to complete.( Survey at Hiap Lek Automobile Trading.)

This survey was conducted on a "WITHOUT PREJUDICE" basis.

S/N	Description	Qty	Condition	Original Quotation	Revised Quotation	
1	Rear Bumper	1	Deformed ✓	1,218.20	1,218.20	1118.20
2	Rear Bumper side @\$120.00	2	Grazed ✓	240.00	240.00	200.00
3	Rear Bumper bracket @\$35.75	2	Bent ✓	71.50	71.50	
4	Rear Bumper side holder@\$112/-	2	Bent ✓	224.00	224.00	
5	Rear Bumper side retainer@\$33.85	2	Dislodge ✓	67.70	67.70	
6	Rear Bumper reflector @\$71.50	2	Grazed X	143.00	143.00	X NN
7	Tailamp @\$569.50	2	Grazed ✓	1,139.00	1,139.00	
8	Tailgate	1	Bent ✓	1,131.80	1,131.80	1076.00
9	Tailgate lock	1	Bent ✓	391.10	391.10	
10	Tailgate sensor lock	1	Faulty *DM	285.00	285.00	
11	Tailgate 'Centre' emblem	1	Necessary	41.80	41.80	
12	Tailgate inner trim board	1	Usable NN	631.80	0.00	X
13	Tailgate number plate garnish	1	Grazed ✓	281.20	281.20	
14	Tailgate number plate lamp @\$81.20	2	Grazed X NN	162.40	162.40	X
15	Tailgate windscreen glass	1	Shattered ✓	1,187.00	1,187.00	
16	Tailgate windscreen glass moulding	1	Necessary ✓	301.30	301.30	133.70
17	Tailgate weatherstrip	1	Necessary ✓	247.53	247.53	
18	Tailgate reflector @\$230.00	2	Grazed ✓	460.00	460.00	
19	Tailgate hinge @69.80	2	Bent ✓	139.60	139.60	
20	Tailgate damper w/cpu (Accessories)	2	Bent/faulty NN	1,200.00	1,200.00	X
21	Tailgate rubber guide stopper@\$35.30	2	Necessary ✓	70.60	70.60	
22	Tailgate lock catch	1	Bent ✓	30.00	30.00	
23	Tailgate outer handle	1	Grazed ✓	261.80	261.80	
24	Tailgate wiper arm	1	Bent ✓	45.00	45.00	
25	Tailgate wiper arm cover	1	Grazed ✓	12.00	12.00	
26	Tailgate wiper motor	1	Malfunction ✓	511.30	511.30	
27	Roof top	1	Repair R	2,350.00	0.00	X
28	Rear third brake lamp	1	Grazed ✓	65.00	65.00	
29	Rear fender @\$879.80	2	Dented Lh X NN	1,759.60	879.80	X
30	Rear end panel	1	Bent ✓	588.80	588.80	
31	Spare tyre card board (top)	1	Deformed NN	271.80	271.80	X
32	Spare tyre compartment	1	Bent NN	733.80	733.80	X
				15,529.83	11,668.23	
			0 % and 25% discount	0.00	2,917.06	
				15,529.83	8,751.17	

<u>Special nett items</u>					
33	Rear bumper clip	1 set	Necessary	40.00	40.00 ✓
34	Rear bumper sensor	1 set	Faulty Shorted	300.00	300.00 200
35	Rear camera @\$400.00	2	Faulty NN	800.00	800.00 X
36	Tailgate top spoiler	1	Cut ✓	450.00	450.00 350.00
37	Tailgate top spoiler sealant	1	Necessary ✓	80.00	60.00 30.00
38	Tailgate glass primer	1 bot	Necessary ✓	18.00	18.00 18.00
39	Tailgate glass sealant	1	Necessary ✓	80.00	60.00 ✓
40	Rear fender inner trim board clip Lh	1 set	Necessary ✓	28.00	28.00 20
41	Rear end panel garnish clip	1 set	Necessary ✓	28.00	28.00 20
42	Rear end panel sealant	1	Necessary ✓	50.00	50.00 ✓
43	Rear spare tyre panel insulation	1	Necessary NN	150.00	150.00 X
Parts total				17,553.83	10,735.17
<u>Labour &amp; Misc.</u>					
1)	Labour charge to remove-refit, panel beat, straighten, re-align and repair of Rear bumper, rear fender rh, tailamp rh, tailgate, rear end panel and others relevant accident damages.			1,600.00	1,400.00 1200.00
2)	To check wirings, lightings and remove/refix rear bumper reverse sensors.			100.00	80.00 40.00
3)	To supplied and applied anti rust treatment to affected panels.			270.00	210.00 40.00
4)	To remove-refit rear tailgate compartment upholstery, garnish, attachments and etc....., to facilitate repair.			100.00	80.00 60.00
5)	Remove/refix rear new windscreen glass			180.00	120.00 120.00
6)	To vacuum tailgate windscreen glasses			80.00	60.00 X
7)	To remove-refix rear exhaust silencer for repair			100.00	80.00 X
8)	To putty and spray painting charges.			1,400.00	1,200.00 1000.00
Total				21,383.83	13,965.17
Lump sum repair adjustment					11,150.00

L/sum \$ 7800.00  
6days.