6/18/23, 1:29 AM Adjuster Report

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG22006819/UGA3Q2

Date: 18/06/2023

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900082640-03 **Claimant Vehicle** SJP9889R Insured Vehicle No: SMM776Y

Date of Loss: 16/07/2022 Nature of Claim: TP Claim No: 0060953196SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SJP9889R** Reg No:

Make & Model: MERCEDES-BENZ E220D SE, 2.0 (A) Engine No: 65492080149904 Reg. Date: Chassis No: WDD2130042A313312 17/11/2017 (Man. Year: 2017)

Colour: Odometer: 153850 km Silver

1950 cc **Engine Capacity:** Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 275/35 R19 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS      |                                   | Repairer's          | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|---------------------|------------|------------|--------|
| Parts               |                                   | 7,337.70            | 3,783.88   | 3,553.82   | 48.43  |
| Miscellaneous Items |                                   | 0.00                | 0.00       | 0.00       |        |
| Labour              |                                   | 1,960.00            | 720.00     | 1,240.00   | 63.27  |
| Paintwork Labour    |                                   | 0.00                | 0.00       | 0.00       |        |
| Towing              |                                   | 0.00                | 0.00       | 0.00       |        |
|                     | Calculated Gross Total (S\$)      | 9,297.70            | 4,503.88   | 4,793.82   | 51.56  |
|                     | Approved Total (Overridden) (S\$) |                     | 3,600.00   |            |        |
|                     | (S\$)                             | 9,297.70            | 3,600.00   | 5,697.70   | 61.28  |
|                     | + GST 7.00/7.00% (S\$)            | 650.84              | 252.00     | 398.84     | 61.28  |
|                     | Nett Amount (S\$)                 | 9,948.54            | 3,852.00   | 6,096.54   | 61.28  |
|                     | + Car Rental (2.0 x S\$           | 120.00/day) (S\$)   | 240.00     |            |        |
|                     | + Doc/                            | Search Fee (S\$)    | 2.00       |            |        |
|                     | N                                 | ett Liability (S\$) | 4,094.00   |            |        |
|                     | Global Sum                        | Settlement (S\$)    | 4,090.00   |            |        |

**INSPECTION** 

Date of Assignment: 19/07/2022

Fastech Auto Pte Ltd (HQ) Date Inspected: 19/07/2022 Inspected At:

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA **CHEW HSIAO TONG** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

# **Recommended Parts**

| No.   | Qty   | Part No.        | Particulars                     | Condition              | Repairer's | Amount       |
|-------|---|-----------------|---------------------------------|------------------------|------------|--------------|
| 1     | 1   |                 | *REAR BUMPER                    | Dented / Deformed      | 2,665.20 F | *1,722.31 FL |
| 2     | 1   |                 | *REAR BUMPER PDC SENSOR O/S     | Shorted                | 199.00 F   | *199.00 FL   |
| 3     | 6   |                 | *REAR BUMPER PDC HOLDERS        | Necessary              | 75.00 F    | *75.00 FL    |
| 4     | 1   |                 | *REAR BUMPER LOWER DIFFUSER     | Grazed                 | 481.20 F   | *381.00 FL   |
| 5     | 1   |                 | *REAR BUMPER EXHAUST CHROME O/S | Grazed                 | 225.00 F   | *225.00 FL   |
| 6     | 1   |                 | *REAR BUMPER REINFORCEMENT      | Bent                   | 715.00 F   | *688.00 FL   |
| 7     | 1   |                 | *REAR BUMPER SIDE HOLDER O/S    | Not Necessary          | 155.20 F   | *- FL        |
| 8     | 1   |                 | *SET REAR BUMPER CLIPS          | Necessary              | 50.00 F    | *50.00 FL    |
| 9     | 1   |                 | *TAILLAMP O/S                   | Cracked                | 1,212.00 F | *781.50 FL   |
| 10    | 1   |                 | *TAILLAMP LOWER BRACKET O/S     | Cracked                | 105.00 F   | *82.50 FL    |
| 11    | 1   |                 | *REAR END PANEL                 | Repair                 | 1,455.10 F | *- FL        |
| F=Fra | anchise   | part. L=ListIte | emDisc.                         | _                      |            |              |
|       |   |                 |                                 | Sub Total (S\$)        | 7,337.70   | 4,204.31     |
|       | - List Item Discount on L Items 0.00/10.00% (S\$) |                 |                                 |                        |            | 420.43       |
|       |   |                 |                                 | Total Parts (S\$)      | 7,337.70   | 3,783.88     |
|       |   |                 | Report was unsubmitted o        | during this print-out. |            |              |

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No  | Particulars                               | Lab.Type                     | Repairer's | Amount |
|-----|---|------------------------------|------------|--------|
| Lab | <u>our Items</u>                          |                              |            |        |
| 1   | TO CHECK WIRING                           | New                          | 50.00      | 20.00  |
| 2   | TO DISMANTLE & RELACED REAR PDC SENSOR    | New                          | 80.00      | 50.00  |
| 3   | TO DISMANTLE & REFIX CUSHION UPHOLSTERY   | New                          | 120.00     | 0.00   |
| 4   | TO SPRAY RUST PROOFING                    | New                          | 50.00      | 0.00   |
| 5   | TO DIAGNOSTIC & REPROGARMME SYSTEM        | New                          | 180.00     | 50.00  |
| 6   | LABOUR FOR PANEL BEATING & REPLACED PARTS | New                          | 680.00     | 300.00 |
| 7   | TO PUTTY & SPRAY PAINTING                 | New                          | 800.00     | 300.00 |
|     |   | Gross Labour Cost (S\$)      | 1,960.00   | 720.00 |
|     | Report was unsubm                         | itted during this print-out. |            |        |

< END OF ESTIMATES >