

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC6/ A16 22006819/4923

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *5779889R*at Workshop m/s *Rt.*

of _____

Insured: *SMM 7764*

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *\$135k.*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *2* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT *975e*Date: _____ Person Contacted: *LTA 973803*Date / Time Action / Instruction *Rep 20k.*Veh No: *5779889R*Yr Regn: *17/11/17*Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA /*Make: *Mer Benz*Colour: *Silver*Sp. Reading: *153820*

Eng/No: _____

C/No: *WDD2130042A313312*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *245/40 R19*R: *275/35 R19*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6*R/Bal. *6* mmL/Bal. *6* mmD.O.A. *16/07/22*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

TOTAL

28/7/22 L/S \$3600 insured Alan.

Cecilia

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorized
all
moray
19/7/22
1/s \$3600
2 days

VEHICLE No: SJP 9889R

1PC	REAR BUMPER	20/De	1722.31	\$2,665.20	/
1PC	REAR BUMPER PDC SENSOR O/S	short		\$199.00	/
6PCS	REAR BUMPER PDC HOLDERS @\$12.50	all		\$75.00	/
1PC	REAR BUMPER LOWER DIFFUSER	green	381.00	\$481.20	/
1PC	REAR BUMPER EXHAUST CHROME O/S	green		\$225.00	/
1PC	REAR BUMPER REINFORCEMENT	but	688.00	\$715.00	/
1PC	REAR BUMPER SIDE HOLDER O/S	11		\$155.20	X
1SET	REAR BUMPER CLIPS	all		\$50.00	/
1PC	TAILLAMP O/S	one	781.50	\$1,212.00	/
1PC	TAILLAMP LOWER BRACKET O/S	one	102 82.50	\$105.00	/
1PC	REAR END PANEL	R		\$1,455.10	X
				\$7,337.70	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	11 \$120.00	X
TO SPARY RUST PROOFING	11 \$50.00	X
TO DIAGNOSTIC & REPROGARMME SYSTEM	\$180.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$680.00	300
TO PUTTY & SPRAY PAINTING	\$800.00	300
TOTAL	\$9,297.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2- 4204.31
102
3783.87
720
4503.87
202
3603.