

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006820/UCY3Q2**Date:** 12/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00226602102

**Claimant Vehicle
No :** SGT992Z**Insured
Vehicle No :** SMN2914Y

Date of Loss: 15/07/2022

Nature of Claim: TP

Claim
No: SNM22D204959/C02/TANKW**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SGT992Z**

Make & Model: HONDA HR-V, 1.5 (A)

Engine No: L15Z71000680

Reg. Date: 20/10/2015 (Man. Year: 2015)

Chassis No: MRHRU1830FP000358

Colour: Red

Odometer: 73727 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,214.82	1,577.72	637.10	28.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,755.00	7,740.00	1,015.00	11.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,969.82	9,317.72	1,652.10	15.06
+ GST 7.00/7.00% (S\$)	767.89	652.24	115.65	15.06
Nett Amount (S\$)	11,737.71	9,969.96	1,767.75	15.06

INSPECTION

Date of Assignment: 19/07/2022

Date Inspected: 25/07/2022

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Aug 2022)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT992Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
2	1		*DAMPERSTD 5X5	Necessary	6.82 FS	*6.82 FS
3	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
4	1		*CAPPIVOT	Not Necessary	3.90 FS	*- FS
5	1		*FASTENER BW/SHIELD (4 PCS)	Necessary	15.90 FS	*15.90 FS
6	1		*FASTENER B (2 PCS)	Necessary	8.25 FS	*8.25 FS
7	2		*FASTENER AW/SHIELD	Necessary	5.70 FS	*5.70 FS
8	2		*WINDSCREEN SEALANT	Necessary (1 PCS ONLY)	120.00 FS	*60.00 FS
9	1		*TAILGATE COMP	Badly Dented	682.87 FS	*682.87 FS
10	1		*WEATHERSTRIP TAILGATE	Serviceable	78.90 FS	*- FS
11	1		*LOCK ASSYTAILGATE	Serviceable	67.57 FS	*- FS
12	1		*EMBLEMRR	Necessary	11.40 FS	*11.40 FS
13	1		*EMBLEM.RR.I-VTEC	Necessary	12.45 FS	*12.45 FS
14	1		*EMBLEMH	Necessary	8.02 FS	*8.02 FS
15	1		*NUT ,PUSH 3MM (2 PCS)	Necessary	3.15 FS	*3.15 FS
16	1		*FACERR.BUMPER	Deformed	347.77 FS	*347.77 FS
17	1		*CLIP,BUMPER (8 PCS)	Necessary	13.80 FS	*13.80 FS
18	1		*FACER.RR.BUMPER CORNER	Not Necessary	71.47 FS	*- FS
19	1		*SENSOR ASSY PARKING T99	Not Necessary	53.17 FS	*- FS
20	1		*SENSOR ASSYPARKING	Serviceable	70.27 FS	*- FS
21	2		*RETAINER PARKING SENSOR	Not Necessary	106.35 FS	*- FS
22	1		*BUZZER ASSYSMART	Not Necessary	48.07 FS	*- FS
23	1		*ANTENNA ASSYL.F	Not Necessary	47.40 FS	*- FS
24	1		*PANEL COMPRR	Badly Dented	352.65 FS	*352.65 FS
25	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,214.82** **1,577.72**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	150.00
2	REMOVE & RENEW REVERSE SENSORS	New	200.00	160.00
3	BODY JOINT SEALANT	New	100.00	100.00
4	BODY UNDERSIDE COATING	New	100.00	100.00
5	APPLY BODY UNDERSIDE COATING	New	200.00	100.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	325.00
7	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
8	REMOVE & INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	350.00
9	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	650.00	450.00
10	REMOVE & INSTALL RR WINDSCREEN	New	650.00	650.00
11	CUT OFF & RENEW RR PANEL ,STRAIGHTEN ALIGN	New	2,800.00	2,600.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,200.00	2,080.00
13	STRAIGHTEN & ALIGN RR FLOOR PANEL	New	325.00	325.00
Gross Labour Cost (\$\$)			8,755.00	7,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >