



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 2797Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP	CUT	250.00	250.00
1	FRONT MUDGUARD	SCRATCHED	210.00	180.00
1	FRONT RH COVER	DENTED	190.00	190.00
1	BRAKE LEVER	BENT	75.00	75.00
1	HANDLE BAR	DISTORTED	125.00	125.00
1	SET MIRROR	DENTED	130.00	130.00
1	HANDLE GRIP	DENTED	90.00	75.00
1	FRONT PANEL RH	CUT	180.00	180.00
1	RH STEP PANEL	DENTED / CUT	175.00	175.00
1	RH LOWER PANEL	DENTED / CUT	160.00	160.00
1	YAMAHA EMBLEM	NECESSARY	80.00	80.00
1	SET BALANCER	DENTED	100.00	84.00
1	EXHAUST GUARD	DENTED / CUT	210.00	210.00
1	PILLION FOOT REG RH	SERVICEABLE	120.00	-
1	RADIATOR GUARD	DENTED / CUT	250.00	195.00
1	ENGINE LOWER GUARD	CRACKED	180.00	180.00
	LESS 10% DISCOUNT		-252.50	-228.90
			2,272.50	2,060.10
	<u>LABOUR</u>			
	REMOVE & REPLACE NEW PARTS ,ALIGN & ETC.		250.00	100.00
	CHECK FORK ALIGNMENT & RE-INSTALL.	NOT NECESSARY	120.00	-
			370.00	100.00
	GRAND TOTAL		2,642.50	2,160.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CS/SMO22006826/Kqy3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.