

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006839/GNY3Q2**Date:** 16/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00048392200		
Claimant Vehicle No :	SKP5786T	Insured Vehicle No :	SJS8796R		
Date of Loss:	16/07/2022	Nature of Claim:	TP	Claim No:	SNM22D204960/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP5786T	Engine No:	1ZRX448845
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104516702
Reg. Date:	24/09/2014 (Man. Year: 2014)	Odometer:	270532 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,973.50	1,319.50	2,654.00	66.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	1,030.00	940.00	47.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,943.50	2,349.50	3,594.00	60.47
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	5,943.50	1,900.00	4,043.50	68.03
+ GST 7.00/7.00% (S\$)	416.05	133.00	283.05	68.03
Nett Amount (S\$)	6,359.55	2,033.00	4,326.55	68.03

INSPECTION

Date of Assignment:	19/07/2022	BLK 9006 TAMPINES ST 93 #01-200
Date Inspected:	20/07/2022 Inspected At:	SINGAPORE 528840
Estimated Period of Repair:	4.0 days	Repairer:Falcon-Air Auto Services Pte Ltd (Sin Ming)

Adjuster: XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Dec 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP5786T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S TAILLAMP	Scratched	460.00 FL	*460.00 FL
2	1		*REAR BUMPER	Deformed	697.00 FL	*697.00 FL
3	1		*O/S REAR BUMPER SIDE RETAINER (LONG)	Not Necessary	109.00 FL	*- FL
4	1		*O/S REAR BUMPER SIDE RETAINER (SHORT)	Not Necessary	89.00 FL	*- FL
5	1		*O/S REAR BUMPER REFLECTOR	Cut	109.00 FL	*109.00 FL
6	1		*O/S REAR RIM	Scratched	1,565.25 FS	*180.00 FS
7	1		*O/S REAR SHOCK ABSORBER	Not Necessary	344.00 FL	*- FL
8	1		*O/S REAR WHEEL HUB	Not Necessary	843.00 FL	*- FL
9	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
10	1		*REAR BUMPER LUGGAGE SCUFF	Necessary	380.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,636.25	1,636.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	662.75	316.50
Total Parts (\$\$)	3,973.50	1,319.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO FIT REVERSE SENSOR IN BUMPER	New	50.00	40.00
3	TO CONDUCT COMPETITIVE FOUR WHEEL ALIGNMENT	New	120.00	60.00
4	TO RUSTPROOF ON DAMAGED PARTS	New	150.00	0.00
5	TO REPLACE O/S REAR UNDERCARRIAGE	New	300.00	0.00
6	TO REPAIR INNER PANEL ,ACCIDENT DAMAGE AREA AND REPLACEMENT OF PARTS	New	500.00	300.00
7	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	750.00	600.00
8	TO FIT TYRE ON NEW RIM INCLUDE BALANCING	New	50.00	0.00
Gross Labour Cost (\$\$)			1,970.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >