

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006841/TCY3Q2**Date:** 05/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00124332105

Claimant Vehicle No : SJZ7683C **Insured Vehicle No :** YM6013J

Date of Loss: 15/07/2022 Nature of Claim: TP Claim No: SNM22D204970/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ7683C**

Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZC38159

Reg. Date: 27/10/2020 (Man. Year: 2019) Chassis No: WAUZZZGA1LA023329

Colour: Grey Odometer: 43002 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,223.42	14,293.17	9,930.25	40.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	1,440.00	2,710.00	65.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,373.42	15,733.17	12,640.25	44.55
Approved Total (Overridden) (S\$)		12,500.00		
Nett Amount (S\$)	28,373.42	12,500.00	15,873.42	55.94

INSPECTION

Date of Assignment: 19/07/2022

Date Inspected: 21/07/2022 Inspected At: JEW Motors (HQ)
60 Jalan Lam Huat Carros Centre #03-72
Singapore 737869

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Apr 2023)	
Parts:	N/A	AUDI Q2 999cc 1.0 TFSI S TRONIC (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ7683C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,117.00 FL	*1,117.00 FL
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	361.00 FL	*- FL
3	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	220.00 FL	*- FL
4	1		*FRONT BUMPER AIR GUIDE GRILLE RH	Not Necessary	189.00 FL	*- FL
5	1		*FRONT BUMPER AIR GUIDE GRILLE LH	Not Necessary	189.00 FL	*- FL
6	1		*FRONT BUMPER END CAP RH	Not Necessary	66.00 FL	*- FL
7	1		*FRONT BUMPER SPOILER	Not Necessary	332.00 FL	*- FL
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	174.00 FL	*- FL
9	1		*FRONT WHEEL SPOILER RH	Not Necessary	38.00 FL	*- FL
10	1		*FRONT WHEEL SPOILER LH	Not Necessary	38.00 FL	*- FL
11	1		*FRONT BUMPER ADAPTER RH	Not Necessary	48.00 FL	*- FL
12	1		*FRONT BUMPER ADAPTER LH	Not Necessary	48.00 FL	*- FL
13	1		*RADIATOR GRILLE ASSEMBLY	Cracked	1,561.00 FL	*1,128.80 FL
14	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	138.00 FL	*- FL
15	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	87.00 FL	*87.00 FL
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	769.00 FL	*578.40 FL
17	1		*FRONT BUMPER GUIDE SECTION RH	Not Necessary	40.00 FL	*- FL
18	1		*FRONT BUMPER GUIDE SECTION LH	Not Necessary	40.00 FL	*- FL
19	1		*FRONT BUMPER TOP COVER	Not Necessary	112.00 FL	*- FL
20	1		*CAUTION STICKER	Not Necessary	16.00 FL	*- FL
21	1		*AIR COND STICKER	Not Necessary	9.00 FL	*- FL
22	1		*FRONT HEADLAMP MOUNTING RH	Cracked	132.00 FL	*132.00 FL
23	1		*FRONT HEADLAMP ASSEMBLY RH	Cracked	5,245.00 FL	*4,124.68 FL
24	1		*FRONT HEADLAMP MOUNTING LH	Not Necessary	132.00 FL	*- FL
25	1		*FRONT HEADLAMP ASSEMBLY LH	Cracked	5,245.00 FL	*4,124.68 FL
26	1		*LIFT CYLINDER RH	Not Necessary	156.00 FL	*- FL
27	1		*LIFT CYLINDER LH	Not Necessary	156.00 FL	*- FL
28	1		*LIFT CYLINDER HOSE RH	Not Necessary	204.00 FL	*- FL
29	1		*LIFT CYLINDER HOSE LH	Not Necessary	204.00 FL	*- FL
30	1		*RADIATOR AIR GUIDE RH	Not Necessary	35.00 FL	*- FL
31	1		*RADIATOR AIR GUIDE LH	Not Necessary	35.00 FL	*- FL
32	1		*RADIATOR SEAL RH OUTER	Not Necessary	8.00 FL	*- FL
33	1		*RADIATOR SEAL LH OUTER	Not Necessary	8.00 FL	*- FL
34	1		*RADIATOR AIR GUIDE UPPER CENTRE	Deformed	25.00 FL	*25.00 FL
35	1		*FRONT BONNET	Bent	2,940.00 FL	*2,231.20 FL
36	1		*FRONT SUPPORT PANEL	Cracked	1,101.00 FL	*1,101.00 FL
37	1		*AIRCON CONDENSER	Not Necessary	604.50 FL	*- FL
38	1		*RADIATOR OUTER	Not Necessary	1,061.00 FL	*- FL
39	1		*RADIATOR INNER	Not Necessary	958.00 FL	*- FL
40	1		*FRONT FENDER WHEEL ARCH GARNISH RH	Deformed	360.00 FL	*322.00 FL
41	1		*FRONT FENDER WHEEL ARCH GARNISH LH	Not Necessary	360.00 FL	*- FL
42	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
43	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
44	1		*SET FRONT BUMPER GRILLE CENTRE CLIPS	Not Necessary	30.00 FS	*- FS
45	1		*SET FRONT BUMPER AIR GUIDE GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
46	1		*SET RADIATOR GRILLE ASSEMBLY CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*SET FRONT FENDER WHEEL ARCH GARNISH CLIPS	Necessary	60.00 FS	*10.00 FS
49	1		*FRONT BONNET SEALANT	Not Necessary	150.00 FS	*- FS
50	2		*FRONT FENDER SEALANT	Not Necessary	300.00 FS	*- FS
51	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,451.50	15,041.76
- List Item Discount on L Items 5.00/5.00% (\$\$)	1,228.08	748.59
Total Parts (\$\$)	24,223.42	14,293.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	1,600.00	600.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,200.00	500.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO APPLY ANTI RUST ON AFFECTED PARTS	New	120.00	30.00
5	TO REMOVE & REFIX AIRCON CONDENSER & TOP UP GAS	New	150.00	100.00
6	TO REMOVE & REFIX RADIATOR & CONDUCT PRESSURE TEST	New	150.00	0.00
7	TO REMOVE & REFIX FRONT HEADLAMP CONTROL UNIT AND POWER MODULE	New	250.00	30.00
8	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
9	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT ,PROGRAMMING & CALIBRATION	New	480.00	150.00
Gross Labour Cost (S\$)			4,150.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >