

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006850/TCY3Q2**Date:** 21/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00001902201

Claimant Vehicle No : SNA8324S **Insured Vehicle No :** SJM7096R

Date of Loss: 07/07/2022 Nature of Claim: TP Claim No: SNM22D204962/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA8324S**

Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGHU778465

Reg. Date: 04/11/2017 (Man. Year: 2017) Chassis No: KMH841CMJU571927

Colour: Grey Odometer: 103638 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,849.28	2,652.88	11,196.40	80.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	970.00	2,980.00	75.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,799.28	3,622.88	14,176.40	79.65
Approved Total (Overridden) (S\$)		2,850.00		
Nett Amount (S\$)	17,799.28	2,850.00	14,949.28	83.99

INSPECTION

Date of Assignment: 15/02/2023

Date Inspected: 19/07/2022 Inspected At: IGNITE MOTOR (HQ)
8 Kaki Bukit Ave 4 #01-54 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA8324S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,910.20 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	129.90 FL	*- FL
3	1		*FRONT BUMPER	Torn	478.50 FL	*478.50 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
5	1		*FRONT BUMPER CENTRE INNER RUBBER SEAL	Not Necessary	29.70 FL	*- FL
6	1		*FRONT BUMPER TOWING COVER	Not Necessary	29.00 FL	*- FL
7	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	35.60 FL	*- FL
8	1		*FRONT BUMPER LH FOG LAMP	Not Necessary	278.40 FL	*- FL
9	1		*FRONT BUMPER LOWER LIP	Not Necessary	78.00 FL	*- FL
10	1		*FRONT BUMPER LOWER STIFFNER	Not Necessary	98.00 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	695.00 FL	*- FL
12	1		*FRONT BUMPER INNER SPONGE	Not Necessary	110.70 FL	*- FL
13	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	34.00 FL	*- FL
14	1		*FRONT BUMPER LH SIDE RETAINER	Deformed	34.00 FL	*34.00 FL
15	1		*FRONT BUMPER RH BRACKET	Not Necessary	26.00 FL	*- FL
16	1		*FRONT BUMPER LH BRACKET	Cracked	26.00 FL	*26.00 FL
17	1		*FRONT BUMPER LH CURTAIN DUCT	Not Necessary	29.40 FL	*- FL
18	1		*FRONT GRILLE	Not Necessary	485.60 FL	*- FL
19	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FL	*- FL
20	1		*FRONT GRILLE EMBLEM	Not Necessary	28.70 FL	*- FL
21	1		*FRONT GRILLE UPPER GARNISH	Not Necessary	78.40 FL	*- FL
22	1		*RH HEADLAMP ASSY	Not Necessary	1,298.80 FL	*- FL
23	1		*RH HEADLAMP LOWER BRACKET	Not Necessary	27.80 FL	*- FL
24	1		*RH HEADLAMP LOCK CLIPS	Not Necessary	4.80 FL	*- FL
25	1		*LH HEADLAMP ASSY	Cut	1,298.80 FL	*1,298.80 FL
26	1		*LH HEADLAMP LOWER BRACKET	Not Necessary	27.80 FL	*- FL
27	1		*LH HEADLAMP LOCK CLIPS	Not Necessary	4.80 FL	*- FL
28	1		*FRONT LH FENDER	Bent	434.80 FL	*434.80 FL
29	1		*FRONT LH FENDER SPLASH SHIELD	Not Necessary	85.70 FL	*- FL
30	1		*SET FRONT LH FENDER SPLASH SHIELD CLIPS	Not Necessary	50.00 FL	*- FL
31	1		*FRONT LH FENDER INNER BRACKET	Not Necessary	43.80 FL	*- FL
32	1		*SUPPORT PANEL	Not Necessary	949.30 FL	*- FL
33	1		*SET SUPPORT PANEL UPPER GARNISH	Not Necessary	50.00 FL	*- FL
34	1		*AIRCON CONDENSER	Not Necessary	745.10 FL	*- FL
35	1		*FRONT AIR DUCT	Not Necessary	98.20 FL	*- FL
36	1		*FRONT LH SPORT RIM (ORIGINAL)	Cut	1,014.00 FL	*1,014.00 FL
37	1		*FRONT LH LOWER ARM	Not Necessary	311.50 FL	*- FL
38	1		*FRONT LH SHOCK ABSORBER TOP MOUNTING	Not Necessary	126.90 FL	*- FL
39	1		*FRONT LH SHOCK ABSORBER	Not Necessary	398.00 FL	*- FL
40	1		*FRONT LH WHEEL BEARING	Not Necessary	451.20 FL	*- FL
41	1		*FRONT LH KNUCKLE ARM	Not Necessary	405.10 FL	*- FL
42	1		*FRONT LH TIE ROD END	Not Necessary	91.50 FL	*- FL
43	1		*FRONT LH DRIVE SHAFT	Not Necessary	783.40 FL	*- FL
44	1		*STEERING RACK AND PINION	Not Necessary	942.80 FL	*- FL
45	1		*FRONT LH DOOR	Not Necessary	1,381.50 FL	*- FL
46	1		*FRONT LH DOOR FRAME BLACK TAPE	Not Necessary	22.30 FL	*- FL

Report was unsubmitted during this print-out.

2/21/23, 10:29 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT LH SIDE MIRROR	Not Necessary	638.60 FL	*- FL
48	1		*FRONT LH TYRE	Not Necessary	550.00 FS	*- FS
49	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS
50	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
51	1		*FRONT LH DOOR SEAL	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					17,131.60	3,316.10
- List Item Discount on L Items 20.00/20.00% (\$)					3,282.32	663.22
Total Parts (\$)					13,849.28	2,652.88
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REINSTALL REPLACE AND REALIGNMENT PARTS.TO PANEL BEAT ,CUT/WELD AND STRAIGHTEN AFFECTED PANELS AND AREAS	New	1,400.00	400.00
2	PUTTY AND SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	SPRAY RUST CHEMICAL COATING ON REPAIRED AND REPLACED PANELS AND AREAS	New	80.00	30.00
5	ADJUST AND TEST DRIVE WHEEL ALIGNMENT SYSTEM (BEFORE AND AFTER)	New	180.00	80.00
6	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	0.00
7	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR TO REFILL AIRCON GAS	New	180.00	0.00
8	REMOVE AND REPLACE RADIATOR ASSY,HOSES AND FAN ASSY TO ASSIST REPAIR TO REFILL COOLANT	New	180.00	0.00
9	REFOCUS AND ADJUST HEADLAMPS ASSY	New	50.00	30.00
10	REMOVE AND REINSTALL FRONT LH DOOR INNER PARTS TO NEW DOOR	New	150.00	0.00
Gross Labour Cost (S\$)			3,950.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >