



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6381E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	NOT NECESSARY	2,549.70	-
1	BOOT LID RUBBER	NOT NECESSARY	187.40	-
2	BOOT LID HINGE (LH/RH) @\$71.30	NOT NECESSARY	142.60	-
2	BOOT LID ABSORBER (LH/RH) @\$86.70	NOT NECESSARY	173.40	-
1	BOOT LID LOCK UPPER	NOT NECESSARY	224.00	-
1	BOOT LID 'H' EMBLEM	NOT NECESSARY	28.00	-
1	EMBLEM-HYBRID	NOT NECESSARY	24.30	-
1	EMBLEM-IONIQ	NOT NECESSARY	31.30	-
1	BOOT LID LAMP(RH)	NOT NECESSARY	822.00	-
1	REAR BUMPER	TORN	459.40	459.40
1	REAR BUMPER REINFORCEMENT	CRACKED	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$188.10	O/S BENT / N/S NOT NECESSARY	376.20	188.10
1	ANTENNA ASSY-SMARTK OUTER	MTG BROKEN	689.50	689.50
1	REAR BUMPER CENTRE MOULDING ASSY	TORN	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	MTG BROKEN	155.00	155.00
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
2	REAR BUMPER SIDE RETAINER (LH/RH) @\$85.80	O/S BROKEN / N/S NOT NECESSARY	171.60	85.80
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE	MTG BROKEN	123.85	123.85
1	REAR BUMPER SIDE UNDER(RH)	BROKEN	123.10	123.10
1	REAR BUMPER REAR HOOK	NOT NECESSARY	94.60	-
1	REAR BUMPER REFLECTOR LAMP(RH)	CUT	82.90	82.90
1	REAR BUMPER TOWING COVER	NOT NECESSARY	98.80	-
1	REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	SOCKET BROKEN	328.60	328.60
1	LICENCE LAMP	MTG BROKEN	193.53	193.53
1	LICENCE LAMP WIRE	NOT NECESSARY	135.80	-
1	TAIL LAMP(RH)	CRACKED	935.40	935.40
1	TAIL LAMP QUARTER PANEL(RH)	NOT NECESSARY	208.90	-
1	REAR PANEL	DENTED	532.00	532.00

Report Ref No. CS/SMR22006854/Dvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ANTENNA ASSY - TRUNK	NOT NECESSARY	689.50	-
1	REAR PANEL GARNISH	BROKEN	346.80	346.80
1	SPARE TYRE HOLDER	NOT NECESSARY	223.10	-
1	SPARE WHEEL LOCK NUT	NOT NECESSARY	89.50	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	892.50	-
1	REAR TRAY TOOLS BOX RH	DEFORMED	675.30	675.30
1	REAR TRAY LUGGS CENTER	DENTED / DEFORMED	354.20	354.20
1	EXHAUST PIPE INSULATOR	NOT NECESSARY	235.00	-
1	EXHAUST SILENCER	NOT NECESSARY	943.50	-
2	EXHAUST PIPE HANGER @\$29.20	NOT NECESSARY	58.40	-
1	REAR FENDER(RH)	TO REPAIR SEE LABOUR	1,768.30	-
1	REAR FENDER SHIELD REAR PIECE (RH)	NOT NECESSARY	173.60	-
1	REAR FENDER SHIELD FRT PIECE (RH)	NOT NECESSARY	165.50	-
1	REAR FENDER AIR-DUCT (RH)	NOT NECESSARY	87.30	-
1	REAR FENDER TRIM BOARD (RH)	NOT NECESSARY	788.75	-
1	ASSY BSD BLIND SPOT RADAR (RH)	BRACKET BENT	1,784.40	1,784.40
	LESS 20% DISCOUNT		-3,834.74	-1,585.19
			15,338.94	6,340.74
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NOT NECESSARY	35.00	-
1	BOOT LID COMFORT CABLINK TEL NO. STICKER (SN)	NOT NECESSARY	30.00	-
1	BOOT LID ADVERTISEMENT LOGO (SN)	NOT NECESSARY	100.00	-
1	REAR NO.PLATE + TRIM COVER (SN)	CRACKED	45.00	45.00
2	REAR WINDSCREEN SEALANT @\$46.00 (SN)	NOT NECESSARY	92.00	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	180.00	180.00
1	SPARE TYRE PANEL TOP COVER SILICON (SN)	NOT NECESSARY	250.00	-
1	REAR FENDER ADVERTISEMENT LOGO (RH) (SN)	NECESSARY	100.00	100.00
			932.00	425.00

Report Ref No. CS/SMR22006854/Dvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL AND REAR FENDER (RH).		2,400.00	800.00
	SPRAY PAINTING CHARGE.		2,000.00	700.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	240.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX EXHAUST PIPE.	NOT NECESSARY	80.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.}		550.00	150.00
	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR.}		550.00	-
			6,370.00	1,840.00
	GRAND TOTAL		22,640.94	8,605.74
	RECOMMENDED COST OF REPAIRS			8,605.74

Report Ref No. CS/SMR22006854/Dvy3m4

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.