

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG122006855/RQY3E2

Date: 14/09/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMCG21014845
Claimant Vehicle No : SHB5261A Insured Vehicle No : GBH9503R
Date of Loss: 18/07/2022 Nature of Claim: TP Claim No: CDMCG22001422

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB5261A
Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZRS096813
Reg. Date: 10/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FU803572673
Colour: Maroon Odometer: 492888 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,151.70	3,823.64	22,328.06	85.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,050.00	1,670.00	4,380.00	72.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,201.70	5,493.64	26,708.06	82.94
Approved Total (Overridden) (\$\$)		4,750.00		
Nett Amount (\$\$)	32,201.70	4,750.00	27,451.70	85.25

INSPECTION

Date of Assignment: 19/07/2022
Date Inspected: 19/07/2022 Inspected At: Strides Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2022)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB5261A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET, FR BUMPER (DISC 25%)	Deformed	99.80 F	*74.85 F
2	1		*GRILLE SUB-ASSY (DISC 25%)	Cracked	335.60 F	*251.70 F
3	1		*COVER, RR BUMPER ASSY (DISC 25%)	Deformed	423.90 F	*317.93 F
4	2		*PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	Necessary	7.60 F	*5.70 F
5	2		*PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	Necessary	7.60 F	*5.70 F
6	2		*PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	Necessary	7.60 F	*5.70 F
7	3		*PAD, RR BUMPER, CTR (DISC 25%)	Necessary	6.60 F	*4.95 F
8	2		*SEAL, RR BUMPER ARM, RH & LH (DISC 25%)	Necessary	22.00 F	*16.50 F
9	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) (10PCS)	Necessary	15.00 F	*11.25 F
10	1		*GUARD, RR BUMPER, LOWER (DISC 25%)	Deformed	558.30 F	*418.73 F
11	1		*COVER, GUARD RR BUMPER LOWER (DISC 25%)	Scratched	14.80 F	*11.10 F
12	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB- (DISC 25%)	Cracked	891.20 F	*668.40 F
13	1		*NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.23 F
14	1		*NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.23 F
15	1		*EMBLEM SUB-ASSY REAR (DISC 25%)	Necessary	46.30 F	*34.73 F
16	1		*REINFORCEMENT FRONT UPPER (DISC 25%)	Bent	691.10 F	*518.33 F
17	1		*ABSORBER, FR BUMPER (DISC 25%)	Cracked	70.30 F	*52.73 F
18	1		*REAR BUMPER REINFORCEMENT (DISC 25%)	Cracked	318.80 F	*239.10 F
19	1		*RETAINER, RR BUMPER, LH (DISC 25%)	Cracked	111.50 F	*83.63 F
20	1		*FILLER, RR BUMPER, LH (DISC 25%)	Cracked	119.90 F	*89.93 F
21	1		*TAIL GATE WEATHERSTRIP, BACK DOOR (DISC 25%)	Cut	360.70 F	*270.53 F
22	1		*LENS & BODY, REAR COMBINATION LAMP, LH (DISC 10%)	Cracked	438.10 F	*394.29 F
23	1		*NUMBER PLATE (SN)	Scratched	35.00 F	*35.00 F
24	1		*NUMBER PLATE FRAME (SN)	Cut	25.00 F	*25.00 F
25	1		*STRIDES LOGO (SN)	Necessary	7.80 F	*7.80 F
26	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
27	1		*SENSOR REVERSE (SN)	Not Working	180.00 F	*180.00 F
28	1		*SUPPORT, FR BUMPER RH	Not Necessary	76.90 F	*- F
29	1		*SUPPORT, FR BUMPER LH	Not Necessary	82.30 F	*- F
30	1		*COVER, FR BUMPER RH	Not Necessary	28.10 F	*- F
31	1		*COVER, FR BUMPER LH	Not Necessary	28.10 F	*- F
32	1		*REINFORCEMENT FRONT UPPER	Not Necessary	691.10 F	*- F
33	1		*ABSORBER, FR BUMPER	Not Necessary	70.30 F	*- F
34	1		*EXTENSION SUB-ASSY, LH	Not Necessary	116.30 F	*- F
35	1		*EXTENSION SUB-ASSY, RH	Not Necessary	116.30 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REINFORCEMENT FRONT LOWER	Not Necessary	238.50 F	*- F
37	1		*ABSORBER, FR BUMPER LOWER	Not Necessary	117.00 F	*- F
38	1		*SEAL, HOOD TO FR END	Not Necessary	24.40 F	*- F
39	1		*EMBLEM ASSY FRONT	Not Necessary	87.10 F	*- F
40	1		*GRILLE, RADIATOR	Not Necessary	165.00 F	*- F
41	10		*CLIPS PIECE, FRT & RR BUMPER	Not Necessary	15.00 F	*- F
42	2		*RETAINER, FR BUMPER, LH & RH	Not Necessary	8.50 F	*- F
43	1		*LAMP ASSY, FOG, RH	Not Necessary	910.20 F	*- F
44	1		*LAMP ASSY, FOG, LH	Not Necessary	910.20 F	*- F
45	1		*UNIT, HEADLAMP, LH	Not Necessary	2,558.90 F	*- F
46	1		*UNIT, HEADLAMP, RH	Not Necessary	2,558.90 F	*- F
47	1		*COMPUTER SUB-ASSY, HEADLAMP, LH	Not Necessary	486.40 F	*- F
48	1		*COMPUTER SUB-ASSY, HEADLAMP, RH	Not Necessary	486.40 F	*- F
49	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F
50	2		*STOPPER, RR BUMPER, RH & LH	Not Necessary	8.60 F	*- F
51	1		*RETAINER, RR BUMPER, RH	Not Necessary	112.70 F	*- F
52	1		*RETAINER, RR BUMPER, LH	Not Necessary	111.50 F	*- F
53	1		*SEAL, RR BUMPER, RH	Not Necessary	85.20 F	*- F
54	1		*SEAL, RR BUMPER, LH	Not Necessary	85.20 F	*- F
55	1		*FILLER, RR BUMPER, RH	Not Necessary	119.90 F	*- F
56	1		*FILLER, RR BUMPER, LH	Not Necessary	119.90 F	*- F
57	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
58	1		*ANTENNA, ELECTRICAL KEY	Not Necessary	60.30 F	*- F
59	2		*REAR BUMPER GROMMET SCREW	Not Necessary	4.40 F	*- F
60	1		*LENS & BODY, REAR COMBINATION LAMP, RH	Not Necessary	438.10 F	*- F
61	1		*LENS & BODY ASSY, RR BUMPER, RH	Not Necessary	486.80 F	*- F
62	1		*LENS & BODY ASSY, RR BUMPER, LH	Not Necessary	486.80 F	*- F
63	1		*COVER, REAR COMBINATION LAMP, RH	Not Necessary	54.00 F	*- F
64	1		*COVER, REAR COMBINATION LAMP, LH	Not Necessary	54.00 F	*- F
65	1		*COVER, REAR FLOOR UNDER, RH	Not Necessary	169.50 F	*- F
66	1		*COVER, REAR FLOOR UNDER, LH	Not Necessary	234.30 F	*- F
67	1		*COVER, REAR FLOOR UNDER, CENTER	Not Necessary	222.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
68	1		*TAIL GATE PANEL SUB-ASSY, BACK DOOR	Not Necessary	929.60 F	*- F
69	1		*TAIL GATE, WEATHERSTRIP, BACK DOOR	Not Necessary	360.70 F	*- F
70	2		*TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	Not Necessary	55.80 F	*- F
71	1		*TAIL GATE GLASS SUB-ASSY, BACK DOOR	Not Necessary	1,569.70 F	*- F
72	1		*TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	Not Necessary	725.90 F	*- F
73	3		*SEAL W/SCREEN	Not Necessary	111.00 F	*- F
74	2		*TAIL GATE BACK DOOR HINGE ASSY, RH & LH	Not Necessary	118.20 F	*- F
75	1		*TAIL GATE LOCK ASSY, BACK DOOR	Not Necessary	452.10 F	*- F
76	1		*TAIL GATE LOCK COVER, BACK DOOR	Not Necessary	25.30 F	*- F
77	1		*TAIL GATE STRIKER ASSY, BACK DOOR	Not Necessary	24.90 F	*- F
78	1		*+LAMP SET, STOP CENTER	Not Necessary	186.50 F	*- F
79	1		*WIRE, TAIL GATE BACK DOOR	Not Necessary	246.80 F	*- F
80	1		*WIRE, TAIL GATE BACK DOOR, NO.2	Not Necessary	246.80 F	*- F
81	1		*END PANEL SUB-ASSY, BODY LOWER BACK	Not Necessary	629.80 F	*- F
82	1		*SPARE TYRE PANEL, PAN, REAR FLOOR	Not Necessary	564.80 F	*- F
83	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
84	1		*COVER, FR BUMPER	Repair	495.50 F	*- F
85	1		*SPOILER SUB-ASSY, REAR	Repair	1,322.10 F	*- F

F=Franchise part.

Total Parts (\$\$) 26,151.70 3,823.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	2,478.00	700.00
2	SPRAY PAINT	New	2,612.00	900.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	0.00
6	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	40.00
8	TO REMOVE AND REFIX REAR WINDSCREEN	New	240.00	0.00
9	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (\$)			6,050.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >