

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006856/VVY3Q2**Date:** 12/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00119112101	
Claimant Vehicle No :	SNC7378H	Insured Vehicle No :	YQ2549K	
Date of Loss:	16/07/2022	Nature of Claim:	TP	Claim No: SNM22D204986/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC7378H		Engine No:	2ZR2N01926
Make & Model:	TOYOTA NOAH, 1.8 (A)		Chassis No:	ZWR800509090
Reg. Date:	11/11/2021 (Man. Year: 2021)		Odometer:	34248 km
Colour:	Black			
Engine Capacity:	1797 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Tourador 5 mm	Rear Left Side:	Tourador 5 mm
Front Right Side:	Tourador 5 mm	Rear Right Side:	Tourador 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,751.80	9,497.20	2,254.60	19.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,320.00	1,000.00	43.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	14,071.80	10,817.20	3,254.60	23.13
+ GST 8.00/8.00% (\$\$)	1,125.74	865.38	260.36	23.13
Nett Amount (\$\$)	15,197.54	11,682.58	3,514.96	23.13

INSPECTION

Date of Assignment:	23/07/2022	
Date Inspected:	20/07/2022	Inspected At: Vin's Auto Pte Ltd (Vin's Auto) Sin Ming AutoCity,, 160 Sin Ming Drive #03-03 Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: VERON CHEN**Manager:** Thevan Thomas Karthikesavan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2023)
Parts:	M1-MPV	TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC7378H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH HEADLAMP	Cracked	3,606.30 FL	*3,606.30 FL
2	1		*FRONT BUMPER	Deformed	663.90 FL	*663.90 FL
3	1		*FRONT BUMPER RH FOG LAMP COVER	Scratched	113.50 FL	*113.50 FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	103.50 FL	*103.50 FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	148.70 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	323.60 FL	*- FL
7	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
8	1		*TAILGATE	Deformed	1,919.30 FL	*1,919.30 FL
9	1		*TAILGATE GLASS LH MOULDING	Necessary	72.80 FL	*72.80 FL
10	1		*TAILGATE GLASS RH MOULDING	Necessary	72.80 FL	*72.80 FL
11	1		*TAILGATE OUTER CHROME GARNISH	Broken	896.60 FL	*896.60 FL
12	1		*TAILGATE INNER TRIMBOARD	Cut	605.10 FL	*596.60 FL
13	1		*TAILGATE RUBBER	Dented	394.70 FL	*394.70 FL
14	1		*TAILGATE LOCK	Serviceable	495.40 FL	*- FL
15	1		*LH TAILLAMP	Cracked	1,446.80 FL	*722.60 FL
16	1		*LH TAILLAMP PANEL	Repair	189.80 FL	*- FL
17	1		*LH CORNER PANEL	Cut	187.50 FL	*187.50 FL
18	1		*LH CORNER PANEL RETAINER	Necessary	170.60 FL	*170.60 FL
19	1		*REAR BUMPER	Cut	573.60 FL	*573.60 FL
20	1		*REAR BUMPER LH REFLECTOR	Cracked	63.40 FL	*63.40 FL
21	1		*REAR BUMPER TOWING COVER	Cut	22.00 FL	*22.00 FL
22	1		*REAR BUMPER LH SIDE RETAINER	Necessary	77.80 FL	*77.80 FL
23	1		*REAR BUMPER KEYLESS SENSOR	Not Necessary	86.30 FL	*- FL
24	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
25	1		*REAR END PANEL	Not Necessary	779.40 FL	*- FL
26	1		*REAR END PANEL TOP TRIM	Not Necessary	162.50 FL	*- FL
27	1		*SPARE TYRE PANEL TOP COVER	Cracked	1,175.40 FL	*1,141.00 FL
28	1		*REAR LH FENDER INNER TRIMBOARD	Cracked	658.40 FL	*658.40 FL
29	1		*REAR LH FENDER RAIL COVER	Distorted	442.70 FL	*442.70 FL
30	1		*REAR WINDSCREEN GUM	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,642.40	12,649.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,890.60	3,152.40
Total Parts (\$\$)	11,751.80	9,497.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
2	TO RESET HEADLAMP SYSTEM	New	280.00	0.00
3	TO REPAIR DAMAGES	New	880.00	600.00
4	TO SPRAY PAINTING	New	980.00	600.00
Gross Labour Cost (\$\$)			2,320.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >