



# 友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No. 203165/00D

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • Legal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK

DATE: 23/07/2022 OUR REF: UAPL1536  
 REPAIR ESTIMATE TO THE MIT-ATTRACTION NO SMD5954P

## REAR ITEM

- 1 REAR BOOT ASSY *Distorted*
- 2 REAR BOOT HINGES *new*
- 1 REAR BOOT LOCK *new*
- 1 REAR BOOT LOCK STRIKER *new*
- 1 REAR BOOT WEATHERSTRIP *new*
- 1 REAR BOOT OUTER CHROME STRIP *new*
- 1 REAR BOOT EMBLEM *new*
- 1 REAR BOOT (ATTRACTION) EMBLEM *new*
- 1 REAR BOOT (MIVEC) EMBLEM *new*
- 2 REAR TAILLAMP ASSY *new*
- 2 REAR TAILLAMP SIDE CLIPS *new*
- 2 REAR TAILLAMP PANEL *new*
- 1 REAR TAIL END PANEL *Distorted*
- 1 REAR TAIL END PANEL AIR DUCT (INNER) *new*
- 1 REAR TAIL END PANEL AIR DUCT (OUTER) *new*
- 1 REAR TAIL END PANEL INNER GARNISH *new*
- 1 REAR SMART KEYLESS SENSOR *new*
- 1 REAR KEYLESS SENSOR JOINT UNIT *new*
- 1 REAR BUMPER FACE *Distorted*
- 2 REAR BUMPER SIDE RETAINERS *new*
- 1 REAR BUMPER CLIPS (1 SET) *new*
- 2 REAR BUMPER LOWER RELETOR *new*
- 1 REAR L/H FENDER ASSY *new*
- 1 REAR R/H FENDER ASSY *new*
- 2 REAR FENDER INNER SIDE GARNISH *new*
- 2 REAR MUD GUARD GARNISH *new*
- 1 REAR WINDSCREEN MOULDING *new*
- 1 REAR SPARE TYRE TOP COVER *new*
- 1 REAR FLOOR PANEL *new*
- 1 REAR EXHAUST BOX *new*
- 2 REAR EXHAUST BOX RUBBER HOLDER *new*

|    |           |    |     |
|----|-----------|----|-----|
| \$ | 948.00    | ✓  | 828 |
| \$ | 384.00    | +  |     |
| \$ | 216.00    | ✓  |     |
| \$ | 58.00     | +  |     |
| \$ | 212.00    | ✓  |     |
| \$ | 258.00    | ✓  |     |
| \$ | 61.00     | ✓  |     |
| \$ | 74.00     | ✓  |     |
| \$ | 58.00     | ✓  |     |
| \$ | 790.00    | ✓  | 670 |
| \$ | 28.00     | ✓  |     |
| \$ | 422.00    | ✓  |     |
| \$ | 515.00    | ✓  |     |
| \$ | 98.00     | ✓  |     |
| \$ | 98.00     | ✓  |     |
| \$ | 187.00    | ✓  |     |
| \$ | 223.00    | ✓  | 91  |
| \$ | 211.00    | ✓  | 96  |
| \$ | 865.00    | ✓  | 765 |
| \$ | 72.00     | ✓  |     |
| \$ | 55.00     | 30 |     |
| \$ | 118.00    | ✓  |     |
| \$ | 913.00    | ✓  | 855 |
| \$ | 913.00    | ✓  | 855 |
| \$ | 442.00    | ✓  |     |
| \$ | 104.00    | X  |     |
| \$ | 187.00    | ✓  | 155 |
| \$ | 255.00    | ✓  | 895 |
| \$ | 966.00    | ✓  |     |
| \$ | 467.00    | X  |     |
| \$ | 56.00     | X  |     |
| \$ | 10,254.00 |    |     |
| \$ | 1,025.40  |    |     |
| \$ | 9,228.60  |    |     |

LESS 10%

## SPECIAL NETT:-

- 1 REAR BUMPER LOWER SPOILER *Distorted*
- 1 REAR BOOT TOP SPOILER *new*
- 1 SET REAR REVERSE SENSOR *new*
- 1 REAR WINDSCREEN GLASS RUBBER GUM *new*
- 1 REAR NUMBER PLATE *new*

|    |          |   |     |
|----|----------|---|-----|
| \$ | 1,200.00 | ✓ | 200 |
| \$ | 800.00   | X |     |
| \$ | 280.00   | ✓ | 200 |
| \$ | 60.00    | ✓ |     |
| \$ | 50.00    | X |     |

## LABOUR CHARGES:-

- TO TOW VEHICLE TO WORKSHOP
- TO DISM/REFIX REAR WINDSCREEN GLASS
- TO SPRAY UNDERCOATING IN REPAIR
- TO DISM/REWIRE DAMAGED PORTION
- TO DISM/RENEW REAR REVERSE SENSOR
- TO DISM/REFIX ROOF LINING, SEAT, GARNISH IN REPAIR
- TO DISM/RENEW REAR EXHAUST PIPE
- TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
- TO PUTTY AND RESPRAY DAMAGED PORTION

|    |           |      |  |
|----|-----------|------|--|
| \$ | 100.00    | 60   |  |
| \$ | 180.00    | 120  |  |
| \$ | 380.00    | 120  |  |
| \$ | 280.00    | 30   |  |
| \$ | 100.00    | 50   |  |
| \$ | 280.00    | 100  |  |
| \$ | 120.00    | 80   |  |
| \$ | 2,800.00  | 2000 |  |
| \$ | 1,800.00  | 1400 |  |
| \$ | 17,658.60 |      |  |

total: 12413.40  
 1/5: 9.9K ✓  
 14 Days