



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22006863/Kqy3e2	
			Date: 17/03/2023	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SG 6080S	Veh. Inspected	XE 4627E
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22002205MFBP	Excess (\$)	0.00
	Assign From	AINI BINTE	Assign Date	19/07/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	SCANIA P410B6X4HZ (A)	c.c	12742
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	YS2P6X40005517832	Colour	RED
	Odometer	201519 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	TRIANGLE	8 mm
	L/H Front Tyre	295/80 R22.5	TRIANGLE	8 mm
	R/H Rear Tyre	295/80 R22.5 (D/D)	TRIANGLE	5/5/3/3 mm
	L/H Rear Tyre	295/80 R22.5 (D/D)	TRIANGLE	5/5/3/3 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT RH DOOR MIRROR. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/05/2022	Inspection Date	21/07/2022
	Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD SINGAPORE 758133		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	