

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22006864/EPA3Q2**Date:** 19/02/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000612814
<b>Claimant Vehicle No :</b>	SMT7550Z	<b>Insured Vehicle No :</b>	SLJ5519T
Date of Loss:	15/07/2022	Nature of Claim:	TP
		Claim No:	202222004341

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMT7550Z</b>	Engine No:	3A92UJD2894
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH003987
Reg. Date:	16/07/2020 (Man. Year: 2019)	Odometer:	39026 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,947.00	5,033.00	2,914.00	36.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,300.00	3,920.00	2,380.00	37.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,247.00</b>	<b>8,953.00</b>	<b>5,294.00</b>	<b>37.16</b>
<b>+ GST 7.00/7.00% (S\$)</b>	997.29	626.71	370.58	37.16
<b>Nett Amount (S\$)</b>	<b>15,244.29</b>	<b>9,579.71</b>	<b>5,664.58</b>	<b>37.16</b>
<b>+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		1,070.00		
<b>Nett Liability (S\$)</b>		<b>10,649.71</b>		

**INSPECTION**

Date of Assignment:	19/07/2022	
Date Inspected:	04/08/2022 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Feb 2023)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT7550Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY ,RH	Cut	1,208.00 FS	*1,208.00 FS
3	1		*FENDER ,FR RH	Dented	639.00 FS	*639.00 FS
4	1		*FACE ,FR BUMPER	Broken	974.00 FS	*974.00 FS
5	1		*BRACKET ,FR BUMPER ,RH	Broken	16.00 FS	*16.00 FS
6	1		*GARNISH ,FR BUMPER ,RH	Not Necessary	154.00 FS	*- FS
7	1		*AIR DAM ,SIDE,FR RH	Not Necessary	18.00 FS	*- FS
8	1		*SHIELD ,FR WHEELHOUSE ,RH	Crushed	99.00 FS	*99.00 FS
9	1		*GARNISH ,FR FENDER	Not Necessary	79.00 FS	*- FS
10	1		*WHEEL DISC	Cut	834.00 FS	*834.00 FS
11	1		*CROSSMEMBER ,FR AXLE NO.1	Not Necessary	877.00 FS	*- FS
12	1		*ARM ASSY ,FR SUSP ,LWR RH	Not Necessary	283.00 FS	*- FS
13	1		*STRUT ,FR SUSP	Bent	461.00 FS	*461.00 FS
14	1		*GEAR & LINK ASSY ,STEERING	Not Necessary	1,473.00 FS	*- FS
15	1		*BEARING ,FR SUSP STRUT	Necessary	9.00 FS	*9.00 FS
16	1		*STOPPER ,FR SUSP STRUT	Necessary	27.00 FS	*27.00 FS
17	1		*KNUCKLE ,RH	Bent	371.00 FS	*371.00 FS
18	1		*BEARING FR WHEEL HUB	Necessary	123.00 FS	*123.00 FS
19	1		*SNAP RING ,FR WHEEL HUB	Necessary	8.00 FS	*8.00 FS
20	1		*HUB ASSY ,FR WHEEL	Necessary	244.00 FS	*244.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	7,947.00	5,033.00
-------------------	----------	----------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT BUMPER ,FRT RH FENDER & AFFECTED AREA REPAIR ON FRT RH DOOR	New	2,560.00	1,280.00
2	PAINT WORK ON FRT BUMPER ,FRT RH FENDER & FRT RH DOOR	New	2,200.00	1,650.00
3	TO APPLY SEALANT ON AFFECTED AREA	New	120.00	0.00
4	PERFORM RUST PREVENTION	New	120.00	40.00
5	CHECK WIRING & CHASSIS ELECTRICA SYSTEM	New	150.00	120.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
7	REPLACE FRONT UNDERCARRIAGE	New	640.00	320.00
8	TO TRANSFER FRT RH RIM INCLUDING BALANCING	New	50.00	50.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	180.00	180.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,300.00</b>	<b>3,920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >