

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22006865/VVY3E2

Date: 21/07/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SHB2989D **Insured Vehicle No :** SMS1380S
Date of Loss: 23/05/2022 Nature of Claim: TP Claim No: DMPC2200213H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB2989D**
Make & Model: HYUNDAI AE IONIQ, 1.6 (A) Engine No: G4LEJU189546
Reg. Date: 30/04/2019 (Man. Year: 2018) Chassis No: KMHC851CVKU141097
Colour: Yellow Odometer: 0 km
Engine Capacity: 1580 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,188.16	872.32	315.84	26.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	880.00	470.00	34.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,538.16	1,752.32	785.84	30.96
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	2,538.16	1,400.00	1,138.16	44.84
+ GST 7.00/7.00% (S\$)	177.67	98.00	79.67	44.84
Nett Amount (S\$)	2,715.83	1,498.00	1,217.83	44.84

INSPECTION

Date of Assignment: 25/05/2022
Date Inspected: 26/05/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2022)
Parts: 143	HYUNDAI AE IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB2989D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*COVER-RR BUMPER	Cut	459.40 FL	*459.40 FL	
2	1		*MOULDING ASSY-RR BUMPER C	Cut	451.25 FL	*451.25 FL	
3	10		*BUMPER COVER CLIP REAR	Necessary	20.00 FL	*20.00 FL	
4	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS	
5	1		*BEAM-RR BUMPER	Serviceable	394.80 FL	*- FL	
6	1		*BRACKET ASSY-RR BUMPER SI	Necessary	55.80 FL	*55.80 FL	
7	1		*DEP REFLECTOR / REFLEX ASSY	Cracked	41.45 FL	*41.45 FL	
					Sub Total (\$\$)	1,472.70	1,077.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	284.54	205.58
					Total Parts (\$\$)	1,188.16	872.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	350.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	REMOVE / REFIX REVERSE SENSOR	New	50.00	30.00
			Gross Labour Cost (\$)	880.00
			1,350.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >