

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006869/EVY3Q2**Date:** 06/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00135912101

**Claimant Vehicle No :** SL300X **Insured Vehicle No :** YP7773B

Date of Loss: 17/07/2022 Nature of Claim: TP Claim No: SNM22D204972/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SL300X**

Make & Model: BMW X3, 2.0 (A) Engine No: F293K342B48B20A

Reg. Date: 02/09/2020 (Man. Year: 2020) Chassis No: WBATS720609C46012

Colour: Black Odometer: 21448 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,673.21	6,327.06	5,346.15	45.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,975.00	5,900.00	5,075.00	46.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>22,648.21</b>	<b>12,227.06</b>	<b>10,421.15</b>	<b>46.01</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,585.37	855.89	729.48	46.01
<b>Nett Amount (\$\$)</b>	<b>24,233.58</b>	<b>13,082.95</b>	<b>11,150.63</b>	<b>46.01</b>

**INSPECTION**

Date of Assignment: 20/07/2022

Date Inspected: 15/08/2022 Inspected At: Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2022)
<b>Parts:</b>	M1-SUV	BMW X3 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SL300X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*REAR SILENCER	Not Necessary	1,373.70 FS	*- FS
3	1		*TAIL PANEL	Not Necessary	542.20 FS	*- FS
4	1		*INTERIOR TAIL TRIM PANEL	Not Necessary	473.90 FS	*- FS
5	1		*TRUNK LID	Dented	2,051.00 FS	*2,051.00 FS
6	1		*REAR BUMPER CARRIER	Not Necessary	776.85 FS	*- FS
7	1		*LH SIDE GUIDE FOR BUMPER	Not Necessary	136.30 FS	*- FS
8	1		*LH BUMPER GUIDE	Not Necessary	163.55 FS	*- FS
9	1		*RH BUMPER GUIDE	Not Necessary	163.55 FS	*- FS
10	1		*REAR BUMPER TOWING LUG COVER (M)	Not Necessary	77.30 FS	*- FS
11	1		*REAR BUMPER PANEL PRIMED (M/PMA)	Dented	1,562.95 FS	*1,562.95 FS
12	1		*SET MOUNTING PDC/PMA SENSOR REAR (M)	Not Necessary	128.65 FS	*- FS
13	1		*REAR BUMPER BOTTOM TRIM PANEL (M)	Broken	372.15 FS	*372.15 FS
14	1		*LOCK TRUNK LID	Not Necessary	230.30 FS	*- FS
15	1		*TRUNK LID POWER LOCK PANEL	Not Necessary	246.55 FS	*- FS
16	1		*SPRING SUPPORT FOR VIBRATION ABSORB	Not Necessary	320.40 FS	*- FS
17	1		*RH SPINDLE DRIVE	Not Necessary	490.55 FS	*- FS
18	10		*BUMP STOP	Not Necessary	33.00 FS	*- FS
19	1		*REAR WINDOW GREEN	Necessary	1,075.05 FS	*1,075.05 FS
20	1		*TRUNK LID GASKET	Not Necessary	152.00 FS	*- FS
21	1		*SET ADHESIVE PADS FOR ACE 2.0	Not Necessary	37.35 FS	*- FS
22	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
23	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
24	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
25	4		*BLIND RIVET NUT M6	Necessary	10.80 FS	*10.80 FS
26	1		*3M S/F CRYSTALLINE REAR WINDSCREEN	Necessary	420.56 FS	*420.56 FS
27	1		*REAR BUMPER BOTTOM REINFORCEMENT	Broken	81.50 FS	*81.50 FS
28	2		*EMBLEM GROMMET	Necessary	1.90 FS	*1.90 FS
29	1		*PLAQUE 82MM	Necessary	72.85 FS	*72.85 FS
30	1		*LETTERING X3	Necessary	65.60 FS	*65.60 FS
31	1		*LETTERING S DRIVE 20I	Necessary	98.35 FS	*98.35 FS
32	1		*SENSOR WIRE FOR SMART OPENER TOP	Crushed	47.25 FS	*47.25 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)**      **11,673.21**      **6,327.06**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE BUMPER REAR PANEL ,TAILGATE AND TAIL END PANEL	New	4,250.00	1,700.00
2	TO SPRAY PAINT BUMPER REAR PANEL ,TAILGATE AND TAIL END PANEL	New	2,819.00	1,972.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO REPLACE BOOTLID SMART OPENER CONTROL UNIT ,TOP AND BOTTOM SENSOR LINE INCLUDING PROGRAM AND CONDUCT CHECK FOR PROPER FUNCTION	New	661.00	627.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
6	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECK FOR LEAK	New	531.00	0.00
7	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
9	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	0.00
10	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
11	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
12	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,975.00</b>	<b>5,900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >