

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22006872/EPA3Q2**Date:** 24/04/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001000276
Claimant Vehicle No :	SND6878H	Insured Vehicle No :	GBJ3555U
Date of Loss:	17/07/2022	Nature of Claim:	TP
		Claim No:	202222005694

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND6878H		
Make & Model:	MERCEDES-BENZ E200, 2.0 AVG (A)	Engine No:	26492030493335
Reg. Date:	31/05/2022 (Man. Year: 2022)	Chassis No:	W1K2130802B054404
Colour:	Grey	Odometer:	3122 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,612.76	9,524.61	2,088.15	17.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	4,820.00	880.00	15.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,312.76	14,344.61	2,968.15	17.14
+ GST 7.00/7.00% (S\$)	1,211.89	1,004.12	207.77	17.14
Nett Amount (S\$)	18,524.65	15,348.73	3,175.92	17.14
+ Car Rental (7.0 x S\$180.00/day) (S\$)		1,260.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,610.73		

INSPECTION

Date of Assignment:	19/07/2022	
Date Inspected:	26/07/2022 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts:	143	MERCEDES-BENZ E200 2.0 AVG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND6878H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH/F HEADLAMP	Broken	3,619.80 FS	*3,619.80 FS
2	1		*LH/F HEADLAMP CONTROL UNIT	Shorted	701.13 FS	*701.13 FS
3	1		*LH/F FENDER	Dented	1,073.57 FS	*1,073.57 FS
4	1		*LH/F INTERMEDIATE LAYER	Not Necessary	12.38 FS	*- FS
5	1		*FRT BUMPER	Broken	1,637.77 FS	*1,637.77 FS
6	1		*LH/F BUMPER BRACKET	Not Necessary	18.16 FS	*- FS
7	1		*LH/F BASIC CARRIER FOR BUMPER	Not Necessary	70.40 FS	*- FS
8	1		*CT/F BASIC CARRIER FOR BUMPER	Not Necessary	117.33 FS	*- FS
9	1		*FRT IMPACT ABSORBER	Not Necessary	203.34 FS	*- FS
10	1		*BONNET	Dented	2,465.78 FS	*2,465.78 FS
11	1		*BONNET LEFT UPPER CATCH	Not Necessary	38.26 FS	*- FS
12	1		*BONNET LEFT LOWER CATCH	Not Necessary	72.19 FS	*- FS
13	1		*FRT CROSS MEMBER	Not Necessary	573.71 FS	*- FS
14	1		*FRT END SUPPORT MEMBER	Not Necessary	982.38 FS	*- FS
15	4		*COMBINATION NUT	Necessary	16.20 FS	*16.20 FS
16	2		*FUSE LINK	Necessary	10.36 FS	*10.36 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)				11,612.76	9,524.61
-------------------	--	--	--	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
3	REMOVE & REPLACE FRONT BUMPER ,FRONT BONNET ,FRONT LEFT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH	New	2,400.00	1,920.00
4	RESPRAY FRONT BUMPER ,FRONT BONNET & FRONT LEFT FENDER	New	2,800.00	2,400.00
Gross Labour Cost (S\$)			5,700.00	4,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >