

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22006873/KPA3Q2**Date:** 24/11/2022**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000532132-01  
**Claimant Vehicle No :** PC4744E **Insured Vehicle No :** SMQ2271C  
 Date of Loss: 18/07/2022 Nature of Claim: TP Claim No: 202222005711JK

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **PC4744E**  
 Make & Model: NISSAN NV350 MICROBUS, 2.5 4DR 5MT ABS (A) Engine No: YD25355197A  
 Reg. Date: 07/04/2016 (Man. Year: 2014) Chassis No: JN1TC2E26Z0001786  
 Colour: Silver Odometer: 102554 km  
 Engine Capacity: 2488 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8  
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 6 mm  
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,807.20	2,491.20	316.00	11.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,870.00	550.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,227.20</b>	<b>4,361.20</b>	<b>866.00</b>	<b>16.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>(S\$)</b>	5,227.20	3,500.00	1,727.20	33.04
<b>+ GST 7.00/7.00% (S\$)</b>	365.90	245.00	120.90	33.04
<b>Nett Amount (S\$)</b>	<b>5,593.10</b>	<b>3,745.00</b>	<b>1,848.10</b>	<b>33.04</b>
<b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,347.00</b>		

**INSPECTION**

Date of Assignment: 20/07/2022  
 Date Inspected: 28/07/2022 Inspected At: Falcon Air Auto Services Pte Ltd (HQ)  
 176 Sin Ming Drive #01-06, Sin Ming Autocare  
 Singapore 575721  
 Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 Nov 2022)	
<b>Parts:</b>	N/A	NISSAN NV350 MICROBUS 2.5 4DR 5MT ABS (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC4744E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,150.00 FL	*1,150.00 FL
2	1		*TAILGATE LOCK	Dented	200.00 FL	*200.00 FL
3	1		*TAILGATE LOCK COVER GARNISH	Missing	35.00 FL	*35.00 FL
4	1		*TAILGATE LOGO	Necessary	50.00 FL	*50.00 FL
5	1		*TAILGATE EMBLEM -NV350	Necessary	60.00 FL	*60.00 FL
6	1		*REAR BUMPER	Buckled	285.00 FL	*285.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	110.00 FL	*110.00 FL
8	2		*REAR BUMPER TOP CLIP	Necessary	8.00 FL	*8.00 FL
9	1		*REAR END PANEL (OUTER)	Bent	160.00 FL	*160.00 FL
10	1		*REAR END PANEL (INNER)	Bent	360.00 FL	*360.00 FL
11	1		*THIRD BRAKE LIGHT	Serviceable	190.00 FL	*- FL
12	1		*70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
13	1		*TAILGATE GLASS SEALANT	Necessary	45.00 FS	*40.00 FS
14	1		*TAILGATE BODY SEALANT	Not Necessary	80.00 FS	*- FS
15	1		*SET REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
16	20		*CLIPS	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,068.00</b>	<b>2,733.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	260.80	241.80
<b>Total Parts (\$\$)</b>	<b>2,807.20</b>	<b>2,491.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE /REFIX TAILGATE GLASS	New	120.00	120.00
2	TO REMOVE /REFIX TAILGATE MECHANISM	New	100.00	60.00
3	TO APPLY BODY SEALANT TO CAR JOINTS	New	100.00	30.00
4	TO RUSTPROOF ACCIDENT DAMAGE AREA	New	100.00	60.00
5	TO CUT OUT /RE-WELD REAR END PANEL INNER /OUTER REPAIR REAR CHASSIS ,REAR FLOOR PANEL INCLUDING REPLACEMENT OF PARTS	New	800.00	700.00
6	TO SPRAY PAINT ON TAILGATE INNER/OUTER ,REAR BUMPER REAR END PANEL ,REAR FLOOR PANEL	New	1,200.00	900.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,420.00</b>	<b>1,870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >