

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22006876/AGVY3E2

Date: 25/08/2022

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002112269		
Claimant Vehicle No :	SLD2580R	Insured Vehicle No :	YN3590Z		
Date of Loss:	16/07/2022	Nature of Claim:	TP	Claim No:	279359

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD2580R	Engine No:	2NR8567161
Make & Model:	TOYOTA SIENTA, 1.5 G (A)	Chassis No:	NSP1707016630
Reg. Date:	09/06/2016 (Man. Year: 2015)	Odometer:	72558 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,741.05	4,768.67	6,972.38	59.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	850.00	2,100.00	71.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,691.05</b>	<b>5,618.67</b>	<b>9,072.38</b>	<b>61.75</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,691.05</b>	<b>4,500.00</b>	<b>10,191.05</b>	<b>69.37</b>

### INSPECTION

Date of Assignment:	19/07/2022	Hua Meng Spray Painting Workshop (HQ)
Date Inspected:	20/07/2022 Inspected At:	No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 417883

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2022)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLD2580R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	1,488.20 FL	*1,350.00 FL
2	1		*REAR RH DOOR VISOR	Necessary	492.60 FS	*60.00 FS
3	1		*REAR RH DOOR GLASS OUTER MOULDING	Deformed	311.80 FL	*195.00 FL
4	1		*REAR RH DOOR PROTECTOR	Deformed	427.20 FL	*268.00 FL
5	1		*REAR RH DOOR LOWER CHROME PROTECTOR	Not Necessary	313.30 FL	*- FL
6	1		*REAR RH DOOR OUTER HANDLE	Not Necessary	427.50 FL	*- FL
7	1		*REAR RH DOOR TOP ROLLER	Not Necessary	439.20 FL	*- FL
8	1		*REAR RH DOOR LOWER ROLLER	Not Necessary	312.90 FL	*- FL
9	1		*REAR RH DOOR INNER LOCK FRONT	Damaged	657.50 FL	*385.00 FL
10	1		*REAR RH DOOR INNER BOARD	Cracked	806.30 FL	*658.00 FL
11	1		*REAR RH DOOR INNER LOCK BACK	Not Necessary	656.80 FL	*- FL
12	1		*REAR RH DOOR POWER WINDOW MOTOR	Not Necessary	656.80 FL	*- FL
13	1		*REAR RH DOOR POWER WINDOW REGULATOR	Damaged	427.90 FL	*285.00 FL
14	1		*REAR RH DOOR ELECTRIC PUMP	Damaged	1,968.90 FL	*1,968.90 FL
15	1		*REAR RH FENDER LOWER GARNISH	Not Necessary	312.50 FL	*- FL
16	1		*REAR FENDER LOWER PROTECTOR	Deformed	430.60 FL	*155.00 FL
17	1		*REAR RH WHEEL BEARING	Not Necessary	840.80 FL	*- FL
18	1		*RH ROCKER PANEL	Repair	1,116.80 FL	*- FL
19	1		*SET REAR RH DOOR FRAME BLACK STICKER	Necessary	205.60 FS	*80.00 FS
20	1		*REAR RH SPORT RIM	Cut	1,966.60 FS	*680.00 FS
21	1		*REAR RH TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>14,639.80</b>	<b>6,084.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	2,898.75	1,316.23
<b>Total Parts (S\$)</b>	<b>11,741.05</b>	<b>4,768.67</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REINSTALL DOOR FITTINGS	New	250.00	80.00
2	REMOVE & REFIX WHEEL ALIGNMENT	New	100.00	0.00
3	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
4	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,300.00	250.00
5	RESPRAY PAINTING	New	1,100.00	400.00
6	TUFF KOTE	New	100.00	40.00
<b>Gross Labour Cost (\$)</b>			<b>2,950.00</b>	<b>850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >