



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 1291P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	1,076.00	1,076.00
1	SIENTA EMBLEM	NECESSARY	66.75	66.75
1	V EMBLEM	NECESSARY	35.50	35.50
1	SET REAR WINDSCREEN MOULDINGS	NECESSARY	75.20	75.20
1	TOYOTA EMBLEM	NECESSARY	66.15	66.15
	LESS 25% DISCOUNT		-329.90	-329.90
			989.70	989.70
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	30.00	30.00
1	SEALANT (SN)	NECESSARY	40.00	40.00
			70.00	70.00
	<u>LABOUR</u>			
	TO DISMANTLE & REFIX REAR WINDSCREEN.		140.00	120.00
	TO TRANSFER REVERSING CAMERA + CABLE.		40.00	40.00
	TO CHECK/CLEAR FAULT CODES AFTER REPAIR.		80.00	80.00
	TO DISMANTLE + RENEW PARTS.		250.00	200.00
	TO SPRAY PAINT.		400.00	300.00
			910.00	740.00
	GRAND TOTAL		1,969.70	1,799.70
	RECOMMENDED COST OF REPAIRS			1,799.70

Report Ref No. CS/AGI22006885/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.