

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006888/DVY3Q2
Date: 22/11/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00009012101
Claimant Vehicle No :	SMM5248Y	Insured Vehicle No :	SLR9287T
Date of Loss:	17/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204987/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM5248Y	Engine No:	CAV081799
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 (A)	Chassis No:	WVWZZZ13Z9V033896
Reg. Date:	09/07/2009 (Man. Year: 2009)	Odometer:	211002 km
Colour:	Grey		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,447.42	6,150.13	22,297.29	78.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,270.00	2,000.00	6,270.00	75.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	36,717.42	8,150.13	28,567.29	77.80
Approved Total (Overridden) (\$\$)		6,500.00		
	36,717.42	6,500.00	30,217.42	82.30
+ GST 7.00/7.00% (\$\$)	2,570.22	455.00	2,115.22	82.30
Nett Amount (\$\$)	39,287.64	6,955.00	32,332.64	82.30

INSPECTION

Date of Assignment:	23/07/2022	
Date Inspected:	21/07/2022 Inspected At:	C.S. Ong Auto Pte Ltd (AMK) 10 Ang Mo Kio Industrial Park 2A, #02-16, AMK Auto Point Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2022)
Parts:	M1-COUPE	VOLKSWAGEN SCIROCCO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM5248Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR ASSY RH	Not Necessary	1,875.60 FL	*- FL
2	1		*FRONT DOOR RH	Dented	2,495.60 FL	*1,575.45 FL
3	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	321.00 FL	*- FL
4	1		*FRONT DOOR WINDOW INNER MOULDING RH	Not Necessary	249.00 FL	*- FL
5	1		*FRONT DOOR WEATHERSTRIP OUTER RH	Not Necessary	384.00 FL	*- FL
6	1		*FRONT DOOR WEATHER STRIP INNER RH	Not Necessary	351.00 FL	*- FL
7	1		*FRONT DOOR INNER TRIM BOARD	Not Necessary	1,139.20 FL	*- FL
8	1		*FRONT DOOR WINDOW MOTOR RH	Not Necessary	845.00 FL	*- FL
9	1		*FRONT DOOR WINDOW REGULATOR RH	Not Necessary	294.00 FL	*- FL
10	1		*FRONT DOOR LOCK RH	Not Necessary	342.00 FL	*- FL
11	1		*FRONT DOOR LOWER GARNISH RH	Cut	298.00 FL	*246.41 FL
12	1		*FRONT DOOR HANDLE RH	Not Necessary	301.00 FL	*- FL
13	1		*REAR FENDER RH	Dented	2,984.50 FL	*1,852.00 FL
14	1		*REAR FENDER INNER PANEL RH	Not Necessary	2,314.20 FL	*- FL
15	1		*REAR FENDER LOWER GARNISH RH	Cut	239.40 FL	*168.60 FL
16	1		*REAR FENDER QUARTER GLASS MOULDING RH	Not Necessary	352.90 FL	*- FL
17	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	1,496.50 FL	*- FL
18	1		*REAR FENDER INNER SHIELD RH	Not Necessary	201.00 FL	*- FL
19	1		*ROCKER PANEL GARNISH RH	Not fitted	1,390.80 FL	*- FL
20	1		*ROCKER PANEL RH	Dented / Cut	982.40 FL	*520.30 FL
21	1		*REAR WHEEL BEARING & HUB ASSY RH	Damaged	473.40 FL	*295.10 FL
22	1		*REAR KNUCKLE ARM RH	Distorted	894.50 FL	*500.17 FL
23	1		*REAR LOWER ARM RH	Distorted	501.20 FL	*389.89 FL
24	1		*REAR CONTROL ARM RH	Not Necessary	495.20 FL	*- FL
25	1		*REAR THRUST ARM RH	Not Necessary	491.00 FL	*- FL
26	1		*REAR UPPER ARM RH	Not Necessary	385.00 FL	*- FL
27	1		*REAR LINKAGE RH	Not Necessary	201.00 FL	*- FL
28	1		*REAR ABSORBER RH	Distorted	789.00 FL	*430.00 FL
29	1		*TAIL LAMP RH	Not Necessary	1,041.00 FL	*- FL
30	1		*TAIL LAMP PANEL RH	Not Necessary	495.00 FL	*- FL
31	1		*REAR BUMPER	Not Necessary	1,781.40 FL	*- FL
32	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	259.00 FL	*- FL
33	1		*RH DOOR CARBON FIBRE HANDLE	Cut	500.00 FS	*150.00 FS
34	1		*SIDE MIRROR CARBON FIBRE COVER	Not Necessary	800.00 FS	*- FS
35	1		*SPORT RIM	Cut	2,000.00 FS	*600.00 FS
36	1		*TYRE	Not Necessary	600.00 FS	*- FS
37	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*SIDE SKIRT CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*20.00 FS
41	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
42	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
44	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$\$)	31,113.80	6,747.92
				- List Item Discount on L Items 10.00/10.00% (\$\$)	2,666.38	597.79
				Total Parts (\$\$)	28,447.42	6,150.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	3,000.00	800.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	3,000.00	700.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	180.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
7	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	60.00
8	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
9	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	300.00	80.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			8,270.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >