

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006897/TCY3Q2**Date:** 02/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00070722200
Claimant Vehicle No :	GBB4363S	Insured Vehicle No :	SDM7878Y
Date of Loss:	11/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204834/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB4363S		
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Engine No:	YD25352456A
Reg. Date:	14/07/2014 (Man. Year: 2014)	Chassis No:	JN1MC2E26Z0002552
Colour:	Grey	Odometer:	260225 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,506.48	505.71	6,000.77	92.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	1,470.00	2,310.00	61.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,286.48	1,975.71	8,310.77	80.79
Approved Total (Overridden) (\$\$)		1,600.00		
Nett Amount (\$\$)	10,286.48	1,600.00	8,686.48	84.45

INSPECTION

Date of Assignment:	26/08/2022		
Date Inspected:	21/07/2022	Inspected At:	Yong Sing Motor Works (HQ) 53 Defu Lane 12 Singapore 539144
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 Aug 2022)	
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB4363S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER	Repair	2,307.47 FL	*- FL
2	1		*REAR RH WHEEL CAP	Cut	295.50 FL	*201.20 FL
3	1		*REAR RH WHEEL	Bent	897.00 FL	*360.70 FL
4	1		*REAR RH SHOCK ABSORBER	Not Necessary	557.75 FL	*- FL
5	1		*REAR RH WHEEL HUB AND BEARING	Not Necessary	526.70 FL	*- FL
6	1		*REAR CROSS MEMBER AXLE	Not Necessary	2,645.00 FL	*- FL
					Sub Total (\$\$)	7,229.42 561.90
					- List Item Discount on L Items 10.00/10.00% (\$\$)	722.94 56.19
					Total Parts (\$\$)	6,506.48 505.71

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR AND REPLACE REAR RH PORTION DAMAGE PARTS DUE TO ACCIDENT	New	2,000.00	600.00
2	REMOVE AND REFIT REAR INNER TRIM TO FACILITATE THE REPAIR	New	150.00	60.00
3	PUTTY AND RESPRAY REAR RH PORTION	New	1,200.00	700.00
4	APPLY ANTI COROSION SEALANT	New	80.00	30.00
5	WHEEL ALIGNMENT	New	100.00	80.00
6	REMOVE REFIT REAR RH UNDERCARRIAGE	New	250.00	0.00
Gross Labour Cost (\$)			3,780.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >