



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 9847P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	617.00	617.00
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	REAR BUMPER LOWER PROTECTOR	DEFORMED	68.00	68.00
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	28.00	-
1	REAR BUMPER LH REFLECTOR	NOT NECESSARY	28.00	-
1	REAR BUMPER LH REFLECTOR COVER	CUT	35.00	35.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	185.00	-
1	REAR END PANEL	NOT NECESSARY	385.00	-
4	REVERSE SENSOR @\$155.00	NOT NECESSARY	620.00	-
1	REAR TRUNK	NOT NECESSARY	654.00	-
1	REAR TRUNK LOGO	NOT NECESSARY	28.00	-
1	REAR TRUNK CIVIC LOGO	NOT NECESSARY	35.00	-
1	REAR TRUNK IVTEC LOGO	NOT NECESSARY	38.00	-
	LESS 20% DISCOUNT		-	-155.00
			2,776.00	620.00
<u>LABOUR</u>				
	TO REMOVE & REFIT REVERSE SENSOR & WIRIRNG.		200.00	30.00
	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS, CUT & WELD IF NECESSARY WITH FULL ALIGNMENT.		1,000.00	200.00
	TO PROVIDE SKILL LABOUR & MATERIAL TO PREPARE FOR PAINT NEW PARTS & PANELS.		800.00	200.00
			2,000.00	430.00
GRAND TOTAL			4,776.00	1,050.00
RECOMMENDED COST OF REPAIRS				1,050.00

Report Ref No. CS/SMR22006898/Tqy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.