

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB22006899/AGA3Q2**Date:** 19/05/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SMV5008B **Insured Vehicle No :** SLW5449T
 Date of Loss: 18/07/2022 Nature of Claim: TP Claim No: MFL2022D0003793

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV5008B**
 Make & Model: TOYOTA VOXY HYBRID, 1.8 V CVT (A) Engine No: 2ZR0C00292
 Reg. Date: 01/10/2020 (Man. Year: 2018) Chassis No: ZWR800332451
 Colour: Bronze Odometer: 173228 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,086.32	1,442.60	4,643.72	76.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,040.00	780.00	2,260.00	74.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,126.32	2,222.60	6,903.72	75.65
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	9,126.32	1,700.00	7,426.32	81.37
+ GST 8.00/8.00% (S\$)	730.11	136.00	594.11	81.37
Nett Amount (S\$)	9,856.43	1,836.00	8,020.43	81.37
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,143.45		

INSPECTION

Date of Assignment: 25/07/2022
 Date Inspected: 25/07/2022 Inspected At: MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM
 Inspection Centre
 Singapore 415933
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Dec 2022)
Parts: M1-MPV	TOYOTA VOXY HYBRID 1.8 V CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV5008B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,080.50 FL	*- FL
2	1		*TAILGATE EMBLEM HYBRID SYNERGY DRIVE	Necessary	82.50 FL	*82.50 FL
3	1		*REAR BUMPER	Deformed	691.30 FL	*691.30 FL
4	1		*REAR BUMPER SIDE RETAINER	O/S Necessary	160.00 FL	*80.00 FL
5	1		*REAR BUMPER REFLECTOR	Cracked	98.20 FL	*98.20 FL
6	1		*REAR CORCER BUMPER	Torn	320.00 FL	*320.00 FL
7	1		*REAR CORCER BUMPER RETAINER	Not Necessary	320.00 FL	*- FL
8	1		*REAR END PANEL	Not Necessary	666.50 FL	*- FL
9	1		*REAR END PANEL TOP GARNISH	Not Necessary	288.90 FL	*- FL
10	1		*REAR BUMPER TOP CHROME	Necessary	280.00 FS	*200.00 FS
11	1		*REAR BUMPER TOP CHROME MAT STICKER	Not Necessary	250.00 FS	*- FS
12	1		*SET REAR BUMPER CLIP	Necessary	25.00 FS	*25.00 FS
13	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	25.00 FS	*- FS
14	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
15	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
16	1		*CEREAMIC DISMOND 9H COATING	Necessary	1,400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,027.90	1,697.00
- List Item Discount on L Items 20.00/20.00% (\$)	941.58	254.40
Total Parts (\$)	6,086.32	1,442.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,000.00	200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	500.00
3	TO TRANSFER TAIL GATE MECHANISM	New	140.00	0.00
4	LABOUR TO REMOVE AND REFIX WINDSCREEN	New	120.00	0.00
5	TUFF COAT	New	180.00	0.00
6	TO CONDUCT WATER LEAKAGE TEST	New	250.00	0.00
7	WIRING CHECK	New	150.00	30.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	100.00	50.00
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	100.00	0.00
Gross Labour Cost (S\$)			3,040.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >