

Vehicle Damage Assessment Report for [SMV5008B]

Estimate Created: 05/08/2022 00:33 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 01/02/2023 07:58 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Voxy
Engine Type			
License Plate Number	SMV5008B	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$1,700.00 WITH 3 DAYS

Insurlogic 5 (01/02/2023 07:44)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
TAILGATE EMBLEM HYBRID SYNERGY		1	82.50	-20.00 %	66.00
REAR BUMPER		1	691.30	-20.00 %	553.04
REAR BUMPER SIDE RETAINER RH		1	80.00	-20.00 %	64.00
REAR BUMPER REFLECTOR		1	98.20	-20.00 %	78.56
REAR CORNER JBUMPER		1	320.00	-20.00 %	256.00
Parts Subtotal					1,017.60

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER TOP CHROME		1.0	200.00	0.00 %	200.00
SET REAR BUMPER CLIP		1.0	25.00	0.00 %	25.00
CERAMIC DISMOND 9H COATING		1.0	200.00	0.00 %	200.00
Materials Subtotal					425.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TO PANEL BEAT, REMOVE AND REPLACE PARTS	RnR	200.00	0.00 %	200.00
WIRING CHECK	RnR	30.00	0.00 %	30.00
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	RnR	50.00	0.00 %	50.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
TAILGATE	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
TO SPRAY PAINT AFFECTED AREA	Full spray	500.00	0.00 %	500.00

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	280.00
		Paint Labor Subtotal	500.00
		<hr/>	
		Labor Subtotal	780.00

Summary

	Repair Cost	2,222.60
	Discount(20 %)	(444.52)
		1,778.08
	Excess	(0.00)
	GST(0.00 %)	0.00
	<hr/>	
	Grand Subtotal	1,778.08