

Insured Veh.

Assign From

Make & Model

Engine No.

Chassis No.

R/H Front Tyre

L/H Front Tyre

R/H Rear Tyre

L/H Rear Tyre

Odometer

Brakes

General

Policy No.

Claim No.

1.

2.

3.

4.

SOMPO INSURANCE SINGAPORE PL

SINGAPORE LAND TOWERSINGAPORE 048623

YN 6456J

HIDDEN

45351 KM

IN ORDER

295/80 R22.5

295/80 R22.5

295/80 R22.5

295/80 R22.5

FAIR

Size

CMTD2202451/RUC

MITSUBISHI FIGHTER

IRENE HENRY

FM65FMA40101

50 RAFFLES PLACE #03-03

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

C.C

Colour

Make

DUNLOP

DUNLOP

DUNLOP

DUNLOP

Steering

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT CS3/SMO22006900/Ecy3m4 Ref: Date: 23/09/2022 Code: SMO Policy Particulars :- (THIRD PARTY CLAIM) YQ 4523X Veh. Inspected Coverage (\$) 0.00 Excess (\$) 0.00 **Assign Date** 20/07/2022 **Vehicle Particulars & Condition** 7545 2021 Year of Reg. **BLUE** IN ORDER STANDARD ALLOY RIM Modification **Conditions of Tyres Balance**

Page No.:1 of 1

Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.



5 mm

5 mm

5 mm

5 mm

5.	General Information				
	Accident Date	15/07/2022	Inspect Date / Time	03/08/2022 (07:00 PM)	
	Survey held at	15 Pioneer Walk #02-01 Singapore 627753			
	Repairer	LYS ENGINEERING			

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
- THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00-\$2,000.00

5b. **Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Report Ref No. CS3/SMO22006900/Ecy3m4

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser