



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 5448J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT LH DOOR SIDE MIRROR}	DAMAGED	2,170.10	890.00
1	FRONT LH DOOR SIDE MIRROR HOUSING}	MISSING	-	-
1	FRONT LH DOOR SIDE MIRROR SIGNAL LAMP	DAMAGED	200.10	89.00
1	FRONT LH DOOR	DENTED	1,339.20	1,215.00
1	FRONT LH DOOR GLASS OUTER MOULDING	NOT NECESSARY	200.30	-
1	FRONT LH DOOR PROTECTOR	CUT	189.50	189.50
1	FRONT LH DOOR TOP HINGE	NOT NECESSARY	190.00	-
1	FRONT LH DOOR LOWER HINGE	NOT NECESSARY	190.00	-
1	FRONT LH DOOR STOPPER	NOT NECESSARY	200.50	-
1	FRONT LH DOOR INNER LOCK	NOT NECESSARY	617.80	-
1	FRONT LH DOOR INNER BOARD	NOT NECESSARY	804.40	-
1	FRONT LH DOOR OUTER HANDLE	NOT NECESSARY	187.10	-
1	FRONT LH DOOR POWER WINDOW MOTOR	NOT NECESSARY	639.20	-
1	FRONT LH DOOR POWER WINDOW REGULATOR	NOT NECESSARY	254.50	-
1	LH DOOR CENTRE PILLAR	NOT NECESSARY	694.50	-
1	REAR LH DOOR	DENTED	1,079.60	1,079.60
1	REAR LH DOOR OUTER GLASS MOULDING	NOT NECESSARY	190.00	-
1	REAR LH DOOR PROTECTOR	CUT	188.60	188.60
1	REAR LH DOOR TOP HINGE	NOT NECESSARY	188.60	-
1	REAR LH DOOR LOWER HINGE	NOT NECESSARY	188.60	-
1	REAR LH DOOR STOPPER	NOT NECESSARY	200.50	-
1	REAR LH DOOR INNER BOARD	NOT NECESSARY	860.10	-
1	REAR LH DOOR POWER WINDOW REGULATOR	NOT NECESSARY	210.60	-
1	REAR LH DOOR POWER WINDOW MOTOR	NOT NECESSARY	617.80	-
	LESS 25% DISCOUNT		-2,900.40	-912.93
			8,701.20	2,738.77
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT LH DOOR FRAME BLACK STICKER (SN)	NECESSARY	188.60	80.00
1	SET REAR LH DOOR FRAME BLACK STICKER (SN)	NECESSARY	133.20	80.00
			321.80	160.00

Report Ref No. CS/SMR22006908/Avy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE & REINSTALL DOOR FITTINGS.		200.00	160.00
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		1,400.00	500.00
	RESPRAY PAINTING.		1,200.00	500.00
	TUFF KOTE.		100.00	50.00
			2,900.00	1,210.00
	GRAND TOTAL		11,923.00	4,108.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CS/SMR22006908/Avy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.