



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22003326/Dqy3e2-1	
			Date: 02/09/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	GBJ 3082S	Veh. Inspected	SKN 1866H	
Policy No.	DMCVSNA00100422100	Coverage (\$)	0.00	
Claim No.	SNM22D202454/C02/LEWLC	Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	18/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WVWZZZ16ZEM026461	Colour	GREY	
Odometer	133352 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	5 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	5 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	09/04/2022	Inspection Date	22/07/2022	
Survey held at	Blk 7 Sin Ming Industrial Estate Sector C #01-82			
Repairer	GUAN AUTO SERVICE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	