

Vehicle Damage Assessment Report for [SMT760E]

Estimate Created: 05/08/2022 00:32 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 04/10/2022 16:31 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Vezel
Engine Type			
License Plate Number	SMT760E	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review based on the information provided by MG Solution PTE LTD: Concluded lump sump repair cost of \$1500 with 3 working days.	Insurlogic 4 (04/10/2022 16:30)
--	---------------------------------

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
FRONT FENDER RH		1	545.00	-20.00 %	436.00
FRONT FENDER WHEEL ARCH		1	185.00	-20.00 %	148.00
Parts Subtotal					584.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
WHEEL RIM (SET)		1.0	450.00	0.00 %	450.00
Materials Subtotal					450.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
TO PANEL BEAT AND REPLACE PARTS	RnR	400.00	0.00 %	400.00
TUFF COAT	RnR	40.00	0.00 %	40.00
WIRING CHECK	RnR	30.00	0.00 %	30.00
FOUR WHEEL ALIGNMENT	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
TO SPRAY PAINT AT AFFECTED AREAS	Full spray	400.00	0.00 %	400.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 550.00

Paint Labor Subtotal 400.00

Labor Subtotal 950.00

Summary

Repair Cost	1,984.00
Discount(24 %)	(484.00)
	1,500.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	1,500.00