

ASS. REQ. BY:

REF:

ASN / 220069141Ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Thiam Hy / Hxx

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 841K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 03 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

/ Est not ready

28/7 11 Pm @ 1700 Cahr

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Fees:

Others:

TOTAL

Veh No: PKL 42705Yr Regn: 11 / 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: KiaColour: RedSp. Reading: 99757

Eng/No: _____

C/No: KNAKU814SE5478811Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: 235/55R19R: Pir

BS / DUN / EKNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 19/7/22

Rear

R/Bal. 3 mmL/Bal. 3 mmD.O.I. 21/7/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rec N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: KIA SORENTO

Engine/Chassis No.: KNAKU814SE5478811

Date of accident: 19.07.22


Damaged area: N/S Rear

Date: 21/07/2022

Claim Type: TP

VRN: SKL4270S

Not Authorized
 11pm @ 1700h
 Resurvey After Rain
 3 days



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear bumper <i>743</i>	<i>CMT</i> 1	\$ 995.00	\$ 995.00	
2	Rear bumper side retainer	<i>Sn</i> 2	\$ 76.00	\$ 152.00	
3	Rear bumper reinforcement	<i>R</i> 1	\$ 495.00	\$ 495.00	
4	Rear bumper side lamp n/s <i>118</i>	<i>CMT</i> 1	\$ 342.00	\$ 342.00	
5	Rear bumper reinforcement bracket	<i>R</i> 2	\$ 95.00	\$ 190.00	
6	Rear bumper lower <i>316</i>	<i>CMT</i> 1	\$ 517.00	\$ 517.00	
7	Rear bumper sponge	<i>Sn</i> 1	\$ 196.00	\$ 196.00	
8	Taillamp n/s	<i>Sn</i> 1	\$ 690.00	\$ 690.00	
9	Taillamp lower panel n/s	<i>R</i> 1	\$ 267.00	\$ 267.00	
10	Bootlid weatherstrip	<i>Sn</i> 1	\$ 195.00	\$ 195.00	
11	End panel	<i>R</i> 1	\$ 590.00	\$ 590.00	
12	End panel top garnish	<i>Sn</i> 1	\$ 263.00	\$ 263.00	
Subtotal				\$ 4,892.00	
List discount				10.00%	
Total				\$ 4,402.80	

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear parking sensor n/s	<i>Sn</i> 1	\$ 280.00	\$ 280.00
2	Rear bumper clips	<i>Sn</i> 12	\$ 5.50	\$ 66.00
3	End panel sealant	<i>Sn</i> 1	\$ 100.00	\$ 100.00
4	End panel top garnish clips	<i>Sn</i> 8	\$ 5.50	\$ 44.00
5	Sundries	<i>Sn</i> 1	\$ 50.00	\$ 50.00
Total				\$ 540.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$	50.00
3	Supply spray paint material and necessary items to respray affected area / panel.	4	\$	800.00
4	To rust proof all affected portions after repair.	0.5	\$	100.00
Total labour			\$	1,950.00

156

4000

X

Estimate Grand Total			\$	6,892.80
----------------------	--	--	----	----------

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: